



# Service Request Details

Claim

S3M04K8W

Reference

CS/HSB23002594/p3 

Loss Date

3 March 2023

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

8 Mar 2023 2:28:24 PM

Request Date

13 March 2023

Due Date

13 March 2024

Services

Pre-Repair Survey

## Actions

---

Next Step

Complete work

More ▾

Vehicle Information

Incident Vehicle Registration #  
GBL8498H

Make  
TPVD Toyota

Model  
Hiace

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

Claim Handler

HO Winnie  
  
winnie.ho@axa.com.sg

Additional Instructions

Messages1	Invoices	History	Documents	Assessment	Metrics	Notes
-----------	----------	---------	-----------	------------	---------	-------

TYPE

SENT

FROM

SUBJECT


BODY

13/3/23 1:58 PM

LKK AUTO CONSULTANTS PTE LTD (TP)

Assignment

Dear Winnie, Thank you for the assignment. Please ...



TYPE

SENT

FROM

SUBJECT


BODY

13/3/23 1:36 PM

HO Winnie

Workshop details

TECH CHOON AUTOMOTIVE PTE LTD 60 Jalan Lam Huat ...



TYPE

SENT

FROM

SUBJECT

BODY

13/3/23 12:41 PM

LKK AUTO CONSULTANTS PTE LTD (TP)

Workshop details

Dear Winnie, Please provide workshop details.

