NCVI BETWEEN MID41697/SNA7461K & SMD9979S AT PIE (TUAS) BETWEEN BEDOK NORTH ROAD AND JALAN EUNOS EXIT ON 21 FEBRUARY 23




Figure 1A: Schematic Diagram detailing accident between SNA7461K & SMD9979S



Figure 2A: Showcases SMD9979S before Accident



Figure 2B: Showcases SMD9979S after collision with MID 41697



Figure 2C: Showcases taxi before accident occurred



Figure 2D: Showcases taxi(SHC228A) after accident between MID 41697 and SMD9979S

STATEMENT FOR INCIDENT AT PIE (TUAS) BETWEEN BEDOK NORTH AND JALAN EUNOS EXIT

On 21 February 23, I, TXXXX088E, CPL LIM ELSTON
was the driver for the operation vehicle (Nissan Sylphy), SNA
7461 K.

At around 0825hrs, I was en-route to Woodlands via PIE (TUAS) as part of Operations. Throughout the journey, my Vehicle Commander reminded me to keep a safe distance from the vehicle in front of me. I was driving as per normal and saw that the yellow taxi in front of me have applied the brakes. I applied the brakes as gradually as possible and came to a stop, that's when a civilian vehicle (SMD 9979 S) rear-ended our vehicle.

Thereafter, my vehicle commander, SXXXX627J, MSG MUHAMMAD TAUFIQ, instructed me to move to the road shoulder, I followed his instructions and the vehicle behind followed. My vehicle commander together with SXXXX276G, MSG HAIQAL BIN ABU KASSIM went down from the vehicle and assessed the damage. They both returned shortly after settling it with the civilian driver and informed us that there were minor scratches on our rear bumper.

Upon receiving approval to resume Operations, my Vehicle Commander instructed me to continue driving to Woodlands.

Figure 3A: Statement of Driver

STATEMENT FOR INCIDENT AT PIE (TUAS) BETWEEN BEDOK NORTH AND JALAN EUNOS EXIT

On 21 February 23, I, SXXXXX627J, MSG MUHAMMAD TAUFIQ BIN MOHD

ZAIN was the Vehicle Commander for the operation vehicle (Nissan Sylphy), SNA 7461 K. Throughout the journey, I reminded my driver to keep a safe distance from the vehicles in front of us.


At around 0825hrs, I was en-route to Woodlands via PIE (TUAS) as part of Operations when a civilian vehicle (SMD 9979 S) rear-ended our vehicle. I immediately instructed the driver, TXXXX088E, CPL LIM ELSTON to move the vehicle to the road shoulder.

Thereafter, I disembarked from the vehicle and assessed the damage. I had also instructed SXXXX276G, MSG HAIQAL BIN ABU KASSIM to disembark and assist in the assessment. I discovered minor scratches on the middle of the rear bumper of our vehicle but did not see any damage on the car that rear ended us.

I proceeded to take photos of the damages and exchanged particulars with the driver, SXXXX263B, MR. SIEW HON MUN (9689 5792). I immediately informed my superiors of the incident

Upon receiving approval to resume Operations, we proceeded to leave the site of incident. That is all.

Figure 3B: Statement of Vehicle Commander



Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Conditio	No of
SNA 7461 K	Car	NISSAN	Sylphy	Silver	Slightly Damaged	5

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SNA 7461 K		- 53		
		-3-	1	

Figure 4A: Police Report part 1





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 3 Report No. T/20230221/7090

CONTINUATION OF REPORT

Details of Perso	n Involved		V3		
Any Pedestrian Ir	nvolved: No		6		
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA		
Passenger			7.6	14	
Name	MUHAMMAD TAUFIC	D ZAIN	ID No.	S 327J	
Related Vehicle	SNA 7461 K (Car)			Contact No.	
Hospital/Clinic	NIL			Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL	•
No. of Days granted Medical Leave NIL			Degree of	Sligh	nt
Point of contact					· O_
Name	MUHAMMAD HAFIZ BIN MAT RAIS			ID No.	S 28Z
Related Vehicle	NIL			Contact No.	
Hospital/Clinic	NIL			Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL	
No. of Days granted Medical Leave NIL		NIL	Degree of	NIL	·

Brief Details.

On 210223, at around 0825H, team were enroute to woodlands via PIE (Tuas) for a visit as part of a periation. When the team exited bedok North Road, slightly before the ERP gantry, the vehicle was rear ended by a civilian vehicle (SMD 9979 S). Elston Lim was the driver for the vehicle, Nissan Sylphy (MID 41697/ SNA 7461K), and Muhammad Taufiq was the front passenger.

There was no injury to personnel onboard.

The wehicle received minor scratches on its rear bumper, and the civilian vehicle did not receive any damage.

Contact info was exchanged between both parties.

Figure 4B: Police Report part 2





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20230221/7090

CONTINUATION OF REPORT

Sketch Plan Informant is not able to provide sketch

Signature Of Informant: Signature Of Officer Recording The Report: The identity of the person making this report has Not applicable been authenticated by Singpass. No signature is required. Signature Of Interpreter. Date/Time: Not applicable 21/02/2023 19:50 Officer In Charge Of Case: Classification Of Case: TP / TPIB / ANG YI TING, STEPHANIE Contact No.: 65476414 NP168

Figure 4C: Police Report part 3