

ASS. REC. BY: Taufik

REF:

1M1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

ChangVeh No: SHD 3537H Yr Regn: 2021, Sep

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 107340 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM HC 85 / CULU / 94622

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 14/5/23Survey held at Confid Logis

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh finalised final fig \$1374.36, 1 day (Red \$0/-, 0%)
FAIR & REASONABLE

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 1Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: MER-TPLump Sum / L.B.R. (T) 1374.36Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)59 Loyang Drive
Singapore 508969
Tel: 6214 8300**TP INSURER:** **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

Singapore

PARTICULARS OF CLAIM

| | | | |
|-------------------------------|--|--------------------|-------------------|
| Claim Type: | THIRD PARTY | Ref. No: | |
| Policy No: | | Date of Loss: | 12/03/2023 |
| Vehicle Reg. No.: | SHD3537H | Driveable? | YES |
| Party At Fault: | UNKNOWN | | |
| Make/Model: | HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A) | Vehicle Reg. Date: | 28/09/2021 |
| Vehicle Colour: | BLUE | Gen Condition: | GOOD |
| Engine No: | G4LEKU429300 | Chassis No: | KMHC851CVLU194622 |
| Odometer: | 107340 KM | | |
| Paint Type: | | | |
| List Item Discount: | 20.00 % | | |
| Total Loss? | NO | | |
| Est. Duration of Repair (day) | 1 | | |
| Present Location: | COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) | | |

COST OF CLAIMS

| | Amount |
|--------------------------|-----------------|
| Parts | 1,113.36 |
| Miscellaneous Items | 11.00 |
| Labour | 250.00 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| Gross Total (S\$) | 1,374.36 |
| + GST 8.00% (S\$) | 109.95 |
| Nett Amount (S\$) | 1,484.31 |

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 13 Mar 2023) |
| Parts: 143 | HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: ComfortDelGro Engineering Pte Ltd/SHD3537H/13/03/2023 14:06 | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk * |

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|--|-----|----------|----------------------|-------|-------|-------------|
| 1 | 1 | | *DOOR WING MIRROR RH | 20.00 | 0.00 | 1,391.70 FL |
| F=Franchise part. L=ListItemDisc. | | | | | | |
| Sub Total (\$\$) | | | | | | 1,391.70 |
| - List Item Discount on L Items (\$\$) | | | | | | 278.34 |
| Total Parts (\$\$) | | | | | | 1,113.36 |

ComfortDelGro Engineering Pte Ltd/SHD3537H/13/03/2023 14:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

| No | Qty | Particulars | Amount |
|----------------------------|-----|----------------------|--------|
| Miscellaneous Items | | | |
| 1 | 1 | OD/TP Case (Insurer) | 11.00 |
| Sub Total (S\$) | | | 11.00 |

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|-------------------------|----------------|----------|--------|
| Labour Items | | | |
| 1 | PANEL BEATING | New | 150.00 |
| 2 | SPRAY PAINTING | New | 100.00 |
| Gross Labour Cost (S\$) | | | 250.00 |

ComfortDelGro Engineering Pte Ltd/SHD3537H/13/03/2023 14:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanji 97495749
'WP' 14/3/23 e 130pm
o/d day
p/p ready before paint
tanji C/whatsapp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508989

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

329 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768731

Date/Time: 13.03.2023 13:56

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5889176

JC NO 305548313

STOMER
/MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
.. (R) 65508755 (O)
(P)

COUNT CARD NO.


| | |
|-----------------------------------|----------------------------------|
| REGN NO: SHD3537H | MILEAGE |
| MAKE: HYUNDAI | FUEL E.....1/2.....F |
| MODEL IONIQ(G3) | DATE/TIME IN 12.03.2023 14:15 |
| YR OF MANU. 28.09.2021 | TARGET DATE |
| CHASSIS CODE KMHC851CVLU194622 | COMPLETION DATE/TIME: |

JOB DESCRIPTION

Accident Date: 12.03.2023

NATURE: 3P 12.03.2023

3/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHD3537H

CHIANG

Vehicle No.:

SHD3537H

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard