

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)59 Loyang Drive
Singapore 508969
Tel: 6214 8300**TP INSURER:** **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	12/03/2023
Vehicle Reg. No.:	SHD3537H	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	28/09/2021
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU429300	Chassis No:	KMHC851CVLU194622
Odometer:	107340 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	1		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,113.36
Miscellaneous Items	11.00
Labour	250.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,374.36
+ GST 8.00% (S\$)	109.95
Nett Amount (S\$)	1,484.31

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2023)
Parts: 143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHD3537H/13/03/2023 14:06	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*DOOR WING MIRROR RH	20.00	0.00	1,391.70 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)						1,391.70
- List Item Discount on L Items (\$\$)						278.34
Total Parts (\$\$)						1,113.36

ComfortDelGro Engineering Pte Ltd/SHD3537H/13/03/2023 14:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	150.00
2	SPRAY PAINTING	New	100.00
Gross Labour Cost (S\$)			250.00

ComfortDelGro Engineering Pte Ltd/SHD3537H/13/03/2023 14:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanji 97495749
'WP' 14/3/23 @ 1300h
01 day
p/p ready before paint
tanji C / hantab.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508989

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

329 Ubi Road Singapore 408649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768731

Date/Time: 13.03.2023 13:56

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5889176

JC NO 305548313

STOMER
/MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
.. (R) 65508755 (O)
(P)

COUNT CARD NO.


REGN NO: SHD3537H	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 12.03.2023 14:15
YR OF MANU. 28.09.2021	TARGET DATE
CHASSIS CODE KMHC851CVLU194622	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 12.03.2023

NATURE: 3P 12.03.2023

3/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHD3537H

CHIANG

Vehicle No.: SHD3537H

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard