



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/03/2023

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1408L
Case Reference Number	BUS/03/23/7002
Registration Date	6/1/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Theenesh Kumar Narainan
Type of Accident	Side Swipe
Accident Date and Time	4/3/2023 10:33 PM
Accident Reported Date and Time	8/3/2023 11:36 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117887
Special Instruction to ARC,if any	SMB1408L - REAR LEFT PORTION SDR478M (TP) - INSURED WITH AIG
Prepared Date and Time	14/3/2023 8:00 AM
Chassis Number	WMAA22ZZXD7001989
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$795.00
Total Spray Cost	\$878.00	\$708.00
Total Spare Part Cost	\$2,638.07	\$1,720.72
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,841.07	\$3,223.72
Lump Sum Total	\$0.00	\$3,200.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Kok Khoon Goh	Kenneth Kong (LKK)
ARC / Surveyor Sign Off Date	14/03/2023 8:17 AM	14/03/2023 2:33 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/03/2023

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,325.00				\$795.00		
Total Labour			\$1,325.00				\$795.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$878.00				\$708.00		
Total Spray Painting & Panel Beating			\$878.00				\$708.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010298			LAMP,STOP:LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	Replace
6010299			SIGNAL LAMP LED	0.00	\$1,274.10	0.00	\$0.00	Replace	Not Given
6010060	Body	F01001-CW271	COVER:REAR TAIL LAMP,LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6010372	Body	4001F09-ACCE5021	PANEL,REFLECTOR:RE AR,LH,FOR MAN BUS	1.00	\$107.00	10.00	\$96.30	Replace	Replace
6010371	Body	88-25215-0001	REFLECTOR,TRIM:FOR MAN BUS	1.00	\$77.60	10.00	\$69.84	Replace	Replace
6011408	Body		BUMPER:REAR,CENTRE,MAN A22 'C' SERIES	1.00	\$1,625.00	100.00	\$0.00	Repair	Repair
6011407	Body		DOOR,ENGINE:REAR,MAN A22 'C' SERIES	1.00	\$1,625.00	100.00	\$0.00	Repair	Repair
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace
			STICKER 60KM/H	1.00	\$5.00	0.00	\$5.00	Replace	Replace
Total					\$6,905.10		\$2,150.90		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									