

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/03/2023

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works									
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable							
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	795%							
Total Labour	\$1,325.00								
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable							
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00	700%							
Total Spray Painting & Panel Beating	\$878.00								
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable							
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010298			LAMP,STOP:LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	CMA ✓
6010299			SIGNAL LAMP LED	1.00	\$1,274.10	10.00	\$1,146.69	Replace	ARC ✓
6010060	Body	F01001-CW271	COVER:REAR TAIL LAMP,LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Bo ✓
6010372	Body	4001F09-ACCES021	PANEL,REFLECTOR:REAR,LH,FOR MAN BUS	1.00	\$107.00	10.00	\$96.30	Replace	CMA ✓
6010371	Body	88-25215-0001	REFLECTOR,TRIM:FOR MAN BUS	1.00	\$77.60	10.00	\$69.84	Replace	CMA ✓
6011408	Body		BUMPER:REAR,CENTRE,MAN A22 'C' SERIES	1.00	\$1,625.00	100.00	\$0.00	Repair	
6011407	Body		DOOR,ENGINE:REAR,MAN A22 'C' SERIES	1.00	\$1,625.00	100.00	\$0.00	Repair	
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	ARC ✓
			STICKER 60KM/H	1.00	\$5.00	0.00	\$5.00	Replace	ARC ✓
Total					\$8,905.10		\$3,297.59		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

NOT Withheld

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/03/2023

User ID : GohKK2

Section A - Accident Details	
Registration Number	SMB1408L
Case Reference Number	BUS/03/23/7002
Registration Date	6/1/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Theenesh Kumar Narainan
Type of Accident	Side Swipe
Accident Date and Time	4/3/2023 10:33 PM
Accident Reported Date and Time	8/3/2023 11:36 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1408L - REAR LEFT PORTION SDR478M (TP) - INSURED WITH AIG
Prepared Date and Time	14/3/2023 8:00 AM
Chassis Number	WMAA22ZZXD7001989
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$3,297.59	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,500.59	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3 days
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	14/03/2023 8:17 AM	
Signature		<input type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	