

ASS. REC. BY: Kenneth REF: HSB/23002654/K Knp3

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

Massive

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8150K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

3 days

Res.: Yes or No

Lump Sum: _____

1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: _____

Date / Time

Action / Instruction

1 Est NOT ready

13/4 61Rm @ 5000L Cash

and 3 days

(red, \$4237.75, 46%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 14/04/23

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

IDENT

No: SMY 285 J

02 21

M.Car / M.Cycle / Bus / Van / Lorry / Taxi

Truck / Traller or

Volkswagen

Tiguan

Wagon

1395

White

A/C

ending

35234

T.Radio

WVGZ885N7LW903229

Cond: Good / Fair / Poor / Burnt

Inorder / Jammed / Leaked / Burnt or

Inorder / Jammed / Leaked / Burnt or

Nil / S/Rim / STD A/Rim or

F: _____

R: _____

255/45R19

EXNOVA / GY / FS / LIZA / MIC / ORTSL

YOKO or

Pir

P

mm

P

mm

12/3/23

Exam

Rebld

L/Sal

D.O.L

P

20/3/2023

old at

Images: Frt / Rear / O/S / N/S / M/S /

Rear N/S

C / Chassis frame / Body Structure

pair: 3

No. of Trip: 2

Survey Fee:

Transportation

Insp (\$

View (\$

Invs (\$

Send (\$

) S-RS

) Fines

) Others

TOTAL

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Zhang Lihuan
Blk 272 Toh Guan Road
#25-79
Singapore 600272

Vehicle No : SMY 285 J
Make : Volkswagon Tiguan
Year : 2021

Not Notified
6/1/89 @ 5000 ft
Bury After Paint
3 days

Estimate Cost Of Repair

S Nett

Labour Charges

Remove/renew rear exhaust silencer

LLK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date: