6/19/23, 5:23 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB23002663/RPA3Q2

Date: 19/06/2023

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_02

Claimant Vehicle SHB4891M Insured Vehicle No: SNB1732M

Date of Loss: 12/03/2023 Nature of Claim: TP Claim No: MFL2023D0003056

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB4891M

Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A) Engine No: G4LEJU111714

Reg. Date: 24/10/2018 (Man. Year: 2018) Chassis No: KMHC851CVKU115008

Colour: Yellow Odometer: 535995 km

Engine Capacity: 1580 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm
West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	0.00	4,600.00	-4,600.00	
+ GST 8.00/8.00% (S\$)	0.00	368.00	-368.00	
Nett Amount (S\$)	0.00	4,968.00	-4,968.00	
+ Loss of Use (4.0 x S	+ Loss of Use (4.0 x S\$90.00/day) (S\$)			
+ Car Rental (9.0 x S\$120.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		6,434.75		
Global Sum Settlement (S\$)		6,430.00		

INSPECTION

Date of Assignment: 14/03/2023

Ding Automotive Pte Ltd (HQ)
Date Inspected: 15/03/2023 Inspected At: 31 CORPORATION ROAD

Singapore 649825

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/19/23, 5:23 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 May 2023)

Parts: N/A HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB4891M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

6/19/23, 5:23 PM

Report was unsubmitted during this print-out.

< END OF ESTIMATES >