

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial Vehicles

Quotation

Non binding - Preview

LKK
16.3.2023 @ 4.30pm

Page 1/3

Company
ERGO INSURANCE PTE. LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER THREE
Singapore 038988

Customer Details:
Mr
LIM
YONG KOK
104A DEPOT ROAD
#03-551
SINGAPORE 101104

Document no.
Document date 14-03-2023
Customer no. 5211001034
Customer GST-ID 199305211H
Dealer 30001
Job order number 2023007224/ 1
Job order date 14-03-2023
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SDH2896D	NS74RZS0	29-04-2019	TMBMD9NS6J8092982	Kodiaq Style 2.0 I TSI 132kW DSG	50,205

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR				#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
9801B003	B&P WHEEL ALIGNMENT				#6	360.00	388.80
9801B001	R&R RIM & BALANCE				#6	50.00	54.00
9801B001	CHANGE LANE ASSIST SYSTEM CALIBRATION				#6	840.00	907.20
565807421	Cover For REAR BUMPER (UPPER)	1	pcs.	2,208.62	#6	2,208.62	2,385.31
565807521 9B9	Cover For REAR BUMPER (LOWER)	1	pcs.	473.82	#6	473.82	511.73
565919493A 9B9	Sensor Bracket	1	pcs.	19.51	#6	19.51	21.07
565919494A 9B9	Sensor Bracket	1	pcs.	19.51	#6	19.51	21.07
565919491C	Sensor Bracket	1	pcs.	15.25	#6	15.25	16.47
565919491B	Sensor Bracket	1	pcs.	15.25	#6	15.25	16.47
565919492B	Sensor Bracket	1	pcs.	15.25	#6	15.25	16.47
565919492C	Sensor Bracket	1	pcs.	15.25	#6	15.25	16.47
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	#6	84.64	91.41
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	#6	74.37	80.32
565807393	Guide Piec LHR BUMPER BRACKET (SIDE)	1	pcs.	57.96	#6	57.96	62.60
565807394	Guide Piec RHR BUMPER BRACKET (SIDE)	1	pcs.	57.96	#6	57.96	62.60
565807393B	Guide Piec LHR BUMPER BRACKET (UPPER)	1	pcs.	57.96	#6	57.96	62.60
565807394B	Guide Piec RHR BUMPER BRACKET (UPPER)	1	pcs.	57.96	#6	57.96	62.60
N 10621301	Expanding Nut	6	pcs.	2.06	#6	12.36	13.35
565945208A	Taillight RHS TAILLIGHT OUTER	1	pcs.	1,037.34	#6	1,037.34	1,120.33
565945308C	Led Tail L RHS TAILLIGHT INNER	1	pcs.	755.54	#6	755.54	815.98
3T0945229	Ball Screw	2	pcs.	3.25	#6	6.50	7.02
N 90781502	Rivitted Cap Nut	2	pcs.	2.81	#6	5.62	6.07
565945106	Reflector REFLECTOR RH	1	pcs.	53.43	#6	53.43	57.70
5Q0907686C	Control Unit For Blind Sp BLIND SPOT CONTROL UNIT RH		pcs.	1,062.32	#6	1,062.32	1,147.31
565907456A	Bracket BLIND SPOT CONTROL UNIT BRACKET RH		pcs.	29.64	#6	29.64	32.01
565809602C	Sectional RHS REAR FENDER	1	pcs.	2,084.55	#6	2,084.55	2,251.31
D 506KD1A4	2k-Insert Foam	1	pcs.	176.68	#6	176.68	190.81
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	73.44	#6	73.44	79.32

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/3

Company

ERGO INSURANCE PTE. LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER THREE
Singapore 038988

Customer Details:

Mr
LIM
YONG KOK
104A DEPOT ROAD
#03-551
SINGAPORE 101104

Document no.

Document date 14-03-2023
Customer no. 5211001034
Customer GST-ID 199305211H
Dealer 30001
Job order number 2023007224/ 1
Job order date 14-03-2023
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SDH2896D	NS74RZS0	29-04-2019	TMBMD9NS6J8092982	Kodiaq Style 2.0 I TSI 132kW DSG	50,205

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
D 007500A2	Zinc Spray <i>ne</i>	1	pcs.	75.80	#6	75.80	81.86
D 180003M2	2k-Body Adhesive <i>ne</i>	1	pcs.	509.24	#6	509.24	549.98
565845298D JV1	Side Windo <i>3 ne</i>	1	pcs.	645.30	#6	645.30	696.92
	RHR FENDER GLASS <i>3 ne</i>						
D 169300M2	1k Window Adhesive <i>ne</i>	1	pcs.	50.73	#6	50.73	54.79
D 00940104	All Purpose Cleaner <i>ne</i>	1	pcs.	84.67	#6	84.67	91.44
D 00920002	Primer <i>ne</i>	1	pcs.	24.91	#6	24.91	26.90
D 181802M1	Activator <i>ne</i>	1	pcs.	21.62	#6	21.62	23.35
D 00950025	Applicator <i>ne</i>	2	pcs.	9.19	#6	18.38	19.85
565854820A 9B9	RHR Wheel Arch Trim <i>cut</i>	1	pcs.	183.60	#6	183.60	198.29
3C0853586	Grommet <i>ne</i>	8	pcs.	1.88	#6	15.04	16.24
565854950 9B9	Protection <i>3X ne</i>	1	pcs.	337.79	#6	337.79	364.81
	RHR DOOR LOWER GARNISH						
3V0853586	Grommet <i>X ne</i>	8	pcs.	1.50	#6	12.00	12.96
565601025F 8Z8	Alloy Whee <i>5 ne</i>	1	pcs.	1,897.98	#6	1,897.98	2,049.82
311601361	Rubber Valve <i>ne</i>	1	pcs.	3.99	#6	3.99	4.31
	LABOUR <i>85</i>	85	pcs.	840.00	#6	67,200.00	7,257.60
	SPRAY PAINT <i>83</i>	83	pcs.	800.00	#6	24,000.00	4,320.00
	R&R RHR FENDER GLASS	1	pcs.	840.00	#6	420.00	907.20
	R&R REAR LUGGAGE TRIM	1	pcs.	840.00	#6	420.00	907.20
	R&R REAR SEAT	1	pcs.	840.00	#6	420.00	907.20
	RHR FENDER GLASS SOLAR FILM <i>(invoice)?</i>	1	pcs.	200.00	#6	200.00	216.00
	ERGO OD/RECOVERY						
	DOA: 13/3/2023						
	EXCESS:						
	SURVEY BY:						

Quotation valid till 21-03-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	2,010.00	25,791.78	8%	2,224.14	27,801.78	30,025.92
Total	2,010.00	25,791.78		2,224.14	27,801.78	30,025.92

Customer

Service Advisor

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

3/3

Company
ERGO INSURANCE PTE. LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER THREE
Singapore 038988

Customer Details:
Mr
LIM
YONG KOK
104A DEPOT ROAD
#03-551
SINGAPORE 101104

Document no.
Document date 14-03-2023
Customer no. 5211001034
Customer GST-ID 199305211H
Dealer 30001
Job order number 2023007224/ 1
Job order date 14-03-2023
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SDH2896D	NS74RZS0	29-04-2019	TMBMD9NS6J8092982	Kodiaq Style 2.0 I TSI 132kW DSG	50,205

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Handwritten:
Casual
Hp 90010068
9 days
16/03/23 @ 1645
EXCESS: TBA
Revert
Resurvey before paint