

## REF:

## ASSIGNMENT

Veh No: SBP18087 Yr Regn: 2021 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Grandland C.C 1199

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading 62468. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WOVZRHN55M6814448

Gen. Cond: Good / Fair / Poor / Burnt


Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/65 R17.

R: 215/65R17.

	
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO OF

Front

R/Bal. *Sh* mm R/Bal. *Sh* mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 23/03/23

\*Survey held at First Antwerp

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Action / Instruction

TP Allied world.

$mv$  :

PV:

Nett:

☐: Prel. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Transportation:

Add Fee: \$1000 : Site Insp (4)

3 + RS.

Fl. 3/98

Others

Forest Forest :

1. *Journal of the American Medical Association*, 1963; 185: 1000.