

*SC202319000A / CYCLE & CARRIAGE INDUSTRIES PTE LTD ENTRY DATE & TIME: 09/01/2023 13:35 (SGT) SUBMITTED BY: AMANDA ANG VERSION: 1 (09/01/2023 13:35 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 09/01/2023 13:35 (SGT) Reported by Both Date of Accident 06/01/2023 07:15 (SGT) Exact Location of Accident Paya Lebar, Singapore Additional Location Information PIE NEAR PAYA LEBAR / EUNOS EXIT Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

2398

Vehicle Registration Number EW3993.I

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner BENJAMIN PHEY BOON LEONG NRIC No SXXXX499G **Email Address** BENPHEY@GMAIL.COM Mobile Phone No (Phone) +65-98470246 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Toyota Model Estima Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd Policy Number / Cover Note Number GA432473

DRIVER

CC

Name of Driver BENJAMIN PHEY BOON LEONG NRIC No SXXXX499G Date Of Birth 04/08/1983 Occupation Outdoor

Date Of Driving Pass 20/10/2014 'Driving experience 8 YEARS AND 3 MONTHS Gender Male Mobile Number (Phone) +65-98470246 Alt. Phone Number **Email Address** BENPHEY@GMAIL.COM Address 33 TAMPINES CENTRAL 7 Address complement #08-46 Postcode 528614 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

Contact Number

SLH3063P

SLH3063P

Private car



Address	-
Address complement	
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- 1. Rease report correctly the details of the accident to speed up the claims proceed.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Criver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Formby insurance companies is not an admestion of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforeseld.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that :

- (a) My insurer , my workshop and the General insurance Association of Srigapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer (s) who have insured vehicle(s) involved in this accident (at insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers", the insurers law yers/law firms, the Nonetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (f) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (i) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handing antifor dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers "law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sted outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Dale

Witnessed by Reporting Centre Personnel

Sketch Plan

ON 6/1/23 @ ABOUT 7.15AM, I WAS TRAVELLING ALONG PIE, EXTREME RIGHT LANE, IN MY VEHICLE EW 3993J. I WAS APPROACHING NEAR PAYA LEBAR / EUNOS EXIT,
IN MY VEHICLE EW 3993J. I WAS APPROACHING NEAR PAYA LEBAR / EUNOS EXIT,
IN MY VEHICLE EW 3993). I WAS APPROACHING NEAR PAYA LEBAR / EUNOS EXTI,
VEHICLES AHEAD SLOWED DOWN, I REDUCED MY SPEED & KEPT A SAFE DISTANCE
AS WELL, SUDDENLY I FELT AN IMPACT & REALISED VEHICLE SLH 3063P COLLIDED
ONTO MY VEHICLE'S REAR PORTION. NO INJURIES. NO PASSENGERS.
2.
3

Declaration

YWe declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &

Oriver's Signature (It driver is not the policyholder) / Dati

Witnessed by Reporting Centre Personnel













Certificate of Insurance

06196

account number

Note Vanides (Trid-Party Risks and Compensation Rot. Chapter (89). Meter Vanides (Trid-Party Risks and Compensation (Pules, 1960, Rose Transport Act, 1961 (Malleywa), Note: Yelling (Trinsport) Rose (Pules, 1946, 1960, Rose (Pules, 1946)).

Policy details

GA4324T3 / 1 BERHAMIN MIEY BOON LOONG (BERHAMIN PENG Certificate number WENLONG) Policyhelder marmé ACR500075017 Comprehensive Gasantial Chassis number 2AZF18J664 Plan name NCD applicable 30%

EM38631 Yabloje redistration number from 21/02/2022 to 20/02/2023 (both issues inclusive) Period of Insurance Mayennik Singaloosa Limited

Persons or classes of persons entitled to drive*

pulanty person who is driving on the Policyhologia cider or with their permapion.

Provided that the person driving is particular in accordance with the liperaing or other laws or regulations to drive the Motor Vehicle or has been so indemitted and is not pagualthed by order of a Coucl of Law or by respectively an accordance regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

use only for addial, domestic and pressure purposes and for the Policyholder's business

decomply an abusing demonstrating the second management of the project of the contract of the such similar purposés

unvialibra rendered repersive by Section 3 of the Mode Vehicles (Third Party Party and Compensation) Act. (Chapter 189) and Section 86 of the Road Transport Act. 1987.
 Maleysia, are not to be included under these "westings."

SGD 500.00 EXCESS Basic Chin Damage Erbest SGD 100 00 Windstreen Excess

An Additional Expense is applicable as follows

- Additional crosses in application of the Committee of State of the Committee of the Committ WOMENORE

Additional clauses & endorsements to your policy

MRIO.

We hereby satisfy that the bolish to which this Cerolicate relates relissed in accordance with the provision of the Mator Vehicles (Third Party Risks and Compensation) Act. (Chapter 189) and Part IV of the Road Transport Act. 1997 (Malaysia)

AXA Insurance Pte Ltd

Authorised aignoture

Important note

system season arrowed.
Adoptiology are warned that on the sale of a motor vehicle they must supervise the Carthodate of Pourance and the Policy to the meurance company. If the Carthodate of Pourance can then be no restricted a Sub-tury Declaration to the effect must be made. Failure to except with this celegation is an offence under the Adote Vehicle (Third-Paris Peaus and Compensation Act (Sec. 189).
For Plantain Warranty Clause requires the premium to be paid in full within a second certification that there would be no tablety under the policy remaind certificate and teachers.

AXA Insurance Pte Ltd (199903512M) 8 Shenton Way #24 01, AVA Tower Singapore 068811

1 8/2



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

9 Temasek Boulevard, Suntec City Tower Two #42-01B Singapore 038989

E-mail: gears-support@shift-technology.com

GST Registration: M400017735

TAX INVOICE

Date of Request: 10/01/2023

Your Ref No: T22-119176-23-JWW

Dear Sir/Madam,

Date of Accident: 06/01/2023 00:00 (SGT)

Vehicle No: EW3993J

Place of Accident: PIE, Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLH3063P	PIE, Singapore	(31.00)	1	(28.70)
GST Amount				
Total Amount Due (GST Inclusive)				

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.

SJ0G2317000X / JP Knights Pte Ltd ENTRY DATE & TIME: 07/01/2023 19:46 (SGT) SUBMITTED BY: Weine Chieng VERSION: 1 (07/01/2023 19:46 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 07/01/2023 19:46 (SGT) Reported by Driver Date of Accident 06/01/2023 19:15 (SGT) **Exact Location of Accident** PIE. Singapore Additional Location Information TOWARDS CHANGI AFTER BEDOK Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **SLH3063P**

INSURED/POLICYHOLDER

Is company? Yes

Name Of Registered Owner **GRAB RENTALS PTE LTD**

VEHICLE PARTICULARS

Manufacturer Toyota

Model **COROLLA ALTIS**

Variant

Vehicle Category Private hire Transmission Auto CC 1598

INSURANCE COMPANY

Name of Insurance Company India International Insurance Pte Ltd

Policy Number / Cover Note Number D21MFL0000447_02

DRIVER

Name of Driver LIM BOON KIAT (LIN WENJIE)

NRIC No S7516793H

Address BLK 17 PUNGGOL FIELD WALK #13-05

Address complement

Postcode 828747

Does Driver Own Other Vehicles? No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear

Weather Conditions	Raining
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Was anybody injured in the Accident?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Translator's name	3 = 1
Translator's ID	∖-
Translator's phone number	-
Translator's email	2
Original language used in the statement	%E
CIRCUMSTANCES OF ACCIDENT	

ON 06/01/23 AT AROUND 1915HRS I WAS DRIVING VEHICLE A (SLH3063P) AT PIE TOWARDS CHANGI AFTER BEDOK EXIT. AS I WAS IN LANE 1, THERE WAS VEHICLE B(EW3993J) IN FRONT OF ME. AS VEHICLE B BRAKES, I PROCEEDED TO DO THE SAME BUT MY VEHICLE FREE WHEELED AND CAUSED ME TO NOT STOP ON TIME AND BUMP ONTO VEHICLE B. WE STOPPED AND EXCHANGED PARTICULARS AND NO ONE WAS INJURED

ATTACHMENT(S)

Are accident photos available for attachment?

Yes
Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

Insurance Company Name

EW3993J

Toyota

Estima

Veyida

Estima

Private car

BENJAMIN PHEY BOON LOONG

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3, information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy flability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims.
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports, or notices to me, which could involvedisclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (Collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time 07/01/23 1200HRS

FLASH ACCIDENT
REPORTING OFFICER
FRO ZIKRUL

Witnessed by Reporting Centre Personnel

Sketch Plan



A-SLH3063P B-EW3993J Describe Circumstances of the Accident

ON 06/01/23 AT AROUND 1915HRS I WAS DRIVING VEHICLE A (SLH3063P) AT PIE TOWARDS CHANGI AFTER BEDOK EXIT. AS I WAS IN LANE 1, THERE WAS VEHICLE B(EW3993J) IN FRONT OF ME. AS VEHICLE B BRAKES, I PROCEEDED TO DO THE SAME BUT MY VEHICLE FREE WHEELED AND CAUSED ME TO NOT STOP ON TIME AND BUMP ONTO VEHICLE B. WE STOPPED AND EXCHANGED PARTICULARS AND NO ONE WAS INJURED

Declaration

I'We declare the foregoing particulars are true in every respect.

H

FLASH ACCIDENT

FRO ZIKRUL

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Dete & Time 07/01/23 1200HRS

Witnessed by Reporting Centre Personnel









IMAGES #5



















Enquire Vehicle's Insurance Particulars

Enquire Vehicle's Insurance Particulars (As At 06 Jan 2023 / 07:15:00)

Ve	hic	la l	nsu	ran	CP	Dρ	taile	2
WC			H3U	anı	L-C	ИC	Lan	3

Vehicle No.:

SLH3063P

Make Description/Model:

TOYOTA / COROLLA ALTIS CLASSIC 1.6 CVT

Insurance Company Name:

INDIA INT'L INS PTE LTD

Business Transaction Reference No.:

20230109122119568430

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Save as PDF

OK →

Print



You have successfully logged out.

Your last login date and time was 09 Jan 2023, 12:19:39.

To return to ONE.MOTORING, please click here

For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History

S/No.	Asset Type≎	Asset ID:	Transaction Type@	Transaction Amount(S\$)≎	Log Date/Time:
1	Vehicle	SLH30631	P 18.19 Enquire Veh Owner Info (Others) by Law Firm	26.75	09 Jan 2023 / 12:21:19

TOH PAINTING & SERVICES PTE LTD Block 3 Woodlands Road Unit 391C&G Yew Tee Industrial Estate Singapore (677966)

Phone 67631055 Fax 67636151 GST Number 20-0311427-D

TAX INVOICE

BENJAMIN PHEY BOON LOONG 33 TAMPINES CENTRAL #08-46 SINGAPORE 528614

Phone: 9847 0246

Fax:

Invoice Number:

1

103136

\$6,800.00

\$6,800.00

Packing Slip Internal Reference Sales Person Page Order Number Customer Delivery Date 1 0000 EW3993J EW3993J T / ESTIMA 06-Jan-23 01-Feb-23 **Amount Discount** Price Quantity Unit Description Code

LUMP SUM REPAIRS

TO SUPPLY SPARE PARTS, REPAIR / PANEL BEATING, WELDING, WIRING CHECKING, PUTTY AND SPRAY PAINTING & OTHER CHARGES

CONTRACT REPAIR AS RECOMMENDED.

SGD: SEVEN THOUSAND THREE HUNDRED FORTY-FOUR ONLY

Shh

Authorised Signature for TOH PAINTING & SERVICES PTE LTD

Total Net	\$6,800.00
GST	\$544.00
Invoice Total Including GST	\$7,344.00

Constant Appraiser Services Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040 Mobile: 9007 5234 Email: constant_as@yahoo.com.sg

RCB No. 53138015K

INVOICE

To: Benjamin Phey Boon Leong

33 Tampines Central 7

#08-46

Singapore 528614

Date : 27/01/2023

Invoice No

: IV23-01020/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle EW 3993J (Inclusive Of Photographs And Transport Charges) Our reference: CAS/23-01/020	\$581.00
Total	\$581.00

E. & O.E

Constant Appraiser Services



Qualified Automobile Accident Damage Appraisers/Loss Adjusters Blk 2 Rivervale Link, #09-02 Singapore 545040 Mobile: 9007 5234

Email: constant as@yahoo.com.sg RCB No. 53138015K

Automobile Inspection Report

To: Benjamin Phey Boon Leong

Date

27/01/2023

33 Tampines Central 7

#08-46

Reference No : CAS/23-01/020

Singapore 528614

General Information

Registration No.

EW 3993J

Accident Date

06/01/2023

Particulars of Damaged Vehicle

Colour

: Pearl White

Make & Model

Toyota Estima Aeras

Engine Capacity

: 2362 cc

Pre-Accident Condition

Good

Mileage (KM)

: 265105

Engine No.

2AZF180664

Chassis No.

: ACR500075012

Steering

i In Order

Registration Date : 21/08/2008

Brake

: In Order

Tyre Condition

Size

Make

Balance

R/H Front Tyre L/H Front Tyre 215/55R17

BRIDGESTONE BRIDGESTONE 90%

R/H Rear Tyre

215/55R17

BRIDGESTONE

90%

L/H Rear Tyre

215/55R17 215/55R17

BRIDGESTONE

90% 90%

Inspection

Repairer

Toh Painting & Services Pte Ltd

Blk 3C Woodlands Road, 391C/G Yew Tee Industrial Estate, Singapore 677966

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate \$\$9,521.99 Revised Amount

Less Excess

: \$6,800.00 .

Nett Total

: \$6,800.00

Remarks

- (A) Survey was done on 10/01/2023
- (B) Re-survey was done on 12/01/2023
- (C) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (D) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Vehicle No: EW 3993J Our ref: CAS/23-01/020

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		PARTS REPLACEMENT - LIST ITEMS			
1	1pc	Tailgate	Dented/Warped	1,885.80	1,885.80
2	1pc	Tailgate glass moulding	Necessary	182.55	182.55
3	1pc	Tailgate logo	Necessary	68.60	68.60
4	1pc	Tailgate emblem 'Estima'	Necessary	76.95	76.95
5	1pc	Tailgate emblem 'Aeras'	Necessary	61.00	61.00
6	1pc	Tailgate inner lock	Bent/Jammed	581.95	581.95
7	1pc	Tailgate inner pull pocket	Serviceable	89.95) = :
8	1pc	Tailgate inner trim board	Deformed/Broken	481.90	481.90
9	1pc	Tailgate weatherstrip	Distorted	211.35	211.35
10	2pcs	Tailgate stopper @ \$48.60	Necessary	97.20	97.20
11	2pcs	Tailgate stopper striker @ \$45.50	Repair	91.00	
12	1pc	Rear bumper	Dented/Deformed	1,217.86	1,217.86
13	2pcs	Rear bumper tow cover @ \$43.90	Serviceable	87.80	:=:
14	2pcs	Rear bumper reflector @ \$66.90	Serviceable	133.80	.=
15	2pcs	Rear bumper sponge @ \$110.30	Broken	220.60	220.60
16	2pcs	Rear bumper side bracket @ \$68.50	Necessary	137.00	137.00
17	2pcs	Rear bumper side retainer @ \$86.65	Necessary	173.30	173.30
18	1pc	Rear end panel	Dented/Warped	791.85	791.85
19	1pc	Rear end panel garnish – top	Deformed	265.90	265.90
20	1pc	Rear end panel garnish – bottom	Deformed	241.35	241.35
21	1pc	Rear smart keyless antenna	Damaged	199.60	199.60
				7,297.31	6,894.76
		Less 25%		(1,824.32)	(1,723.69)
		PARTS REPLACEMENT – SPECIAL	Sub total	5,472.99	5,171.07
		NETT ITEMS			51
1	1 set	Rear bumper clip	Necessary	55.00	55.00
1 2	1 set	Rear end panel trim clip	Necessary	39.00	39.00
3	1 set	Tailgate glass sealant	Necessary	80.00	80.00
4	1 set	Tailgate glass foam tape	Necessary	65.00	65.00
5	1set	Reverse sensor – 4pcs	Broken	480.00	450.00
6	1 set	Rear number plate with holder	Serviceable	60.00	4
			Part total	6,251.99	5,860.07

Vehicle No: EW 3993J Our ref: CAS/23-01/020

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		LABOUR & MISC. CHARGES			
1		Check rear electrical wiring		40.00	20.00
2		Remove, refix tailgate glass		150.00	120.00
3		Remove, refix rear interior trim to assist repair		100.00	80.00
4		Reinstall tailgate electrical & components to new tailgate		100.00	80.00
5		Remove, refix rear reverse sensor / camera		80.00	60.00
6		Respray undercoating		100.00	60.00
7		Respray painting & etc (Pearl white)		1,500.00	1,200.00
8		Panel beating, cut, weld, remove & replacing above parts		1,200.00	1,000.00
			Grand total	9,521.99	8,480.07
Recommended cost of lump sum repair (To its pre-accident condition)				6,800.00	

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$6,800.00 on a contractual basis. Under normal circumstances, the repair period would be about 5 (Five) working days.

Yours faithfully,

Constant Appraiser Services


Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA

















EW 3993J









EW 3993J

















































