

(08/11/13) Waf
ASS. REC. BY: PERMAN

REF: CS/CT123002702/Rvp3

510I

COT - 2024/JAN

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP/WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKM 1859J

at Workshop m/s PERFORMANCE

of 303, ALEXANDRA RD

Insured: GBL 8399K CT1

Policy No. DMCVSNW00056502200

Claims No. SNM23D201914/C02/LEEPG


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 42K

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: _____ days Res.: Yes or No

Turn Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKM 1859J Yr Regn: 2014 JAN

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 520I AT C.C. 1997

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 117341 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBASA32010D334898

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm

D.O.A. 12/03/23 D.O.I. 11/04/23

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 9K

15/5/23 Final fig \$3868 confirmed by email (red 2688.25, 41%)

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1) _____
Date/Time, File Return to?

2) 15/5/23-typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

Survey Fee:

Transportation: _____

Photos

Others

Report Format : Merimen

Lump Sum / I.B.I. / (\$

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

13 MAR 2023

Estimate No. : B1 65298
Date Estimated : 13/03/2023
Prepared By : Han Kwan Yong

Page No. : 1 of 5

ESTIMATE REPAIR FOR -

ng Kwee Goh
7 jalan haji salam

Singapore 468811

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
KM1859J	WBA5A32010D334898	28/01/2014	520iA	82275

DESCRIPTION

To replace rear bumper

850 ~~1,275.00~~

To respray rear bumper

986 ~~1,038.00~~

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

168 ~~177.00~~

To check electrical wiring system and lighting at the
rear section for proper function.

168 ~~177.00~~

Sundries.

✓ ? 80.00

Total Labour 1: 2,747.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
# Set of mount ? x nn	1	49.50	49.50
RR BUMPER BOTTOM CENTRE GUIDE ? x nn	1	142.80	142.80
RR BUMPER CARRIER ? x nn	1	811.15	811.15
ADAPTOR ? x nn	1	116.45	116.45
REAR BUMPER CENTRE GUIDE ? x nn	1	199.90	199.90
REAR BUMPER PRIMED (PDC) de /	1	1,616.00	1,616.00
EXPANDING RIVET D=8MM ? x nn	10	1.15	11.50
PLUG BLACK D=5MM ? x nn	10	0.95	9.50
REAR LH REFLECTOR X nn	1	41.00	41.00
DECOUPLING RING PDC TORQUE CONVERTE m / nn	2	5.30	10.60
BUMPER PDC SENSOR (A89 IMPERIABLAU) ? x nn	2	373.90	747.80
(DG/SL) ADHESIVE SET K6 ? x nn	1	53.05	53.05

Total Parts : 3,809.25

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : B1 65298
Date Estimated : 13/03/2023
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM1859J	WBA5A32010D334898	28/01/2014	520iA	82275

Claims OD / 3rd Party / Uninsured excess / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess \$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PMS Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended 3 days

Claims OD / 3rd Party / Uninsured excess / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess \$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PMS Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended _____

Claims OD / 3rd Party / Uninsured excess / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 11/04/23 @ 1130 Excess \$ _____

Surveyor's Name RKM Sign _____

Surveyor's Tel 900 10868 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PMS Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	2,747.00
Parts	:	3,809.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	524.50

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	5101
Vehicle No.:	SKM1859J
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Apr 2023
Vehicle Make:	B.M.W.
Vehicle Model:	520i AT D/AB 2WD 4DR LED NAV
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	A1810659N20B20B
Chassis No.:	WBA5A32010D334898
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$46,962.00
Original Registration Date:	28 Jan 2014
First Registration Date:	28 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$52,747.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jan 2024
PARF Rebate Amount:	\$26,373.00
COE Expiry Date:	27 Jan 2024
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$78,700.00
COE Rebate Amount:	\$6,219.00
Total Rebate Amount:	\$32,592.00

The information contained herein is correct as at 12 Apr 2023

OK

BMW 5 Series 520i

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Price

\$47,800

Depreciation ⓘ

\$19,970 /yr

[View models with similar depre](#)

Reg Date

29-Apr-2014

(1yr 16days COE left)

Mileage

121,000 km (13.5k /yr)

Manufactured ⓘ

2013

Road Tax ⓘ

\$1,210 /yr

Transmission

Auto

Dereg Value ⓘ

\$37,444 as of today (change)

OMV ⓘ

\$47,719

COE ⓘ

\$75,010

ARF ⓘ

\$53,807

Engine Cap

1,997 cc

Power

135.0 kW (181 bhp)

Curb Weight ⓘ

1,615 kg

No. of Owners ⓘ

3

Type of Vehicle

Luxury Sedan