

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	INSURANCE (S) PL	Ī	Ref:	CS3/AGI21007565/Dvp3e2-1	
	C/O SEAH ONG & 36 ROBINSON RO SINGAPORE 0688	AD #12-03 CITY HOUSE	I	Date:	28/06/2023	
			(	Code:	AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SDP 9166P	Veh. Inspected		FBH 800S	
	Policy No.	C10007399/CD	Coverage (\$)		0.00	
	Claim No.	23.30503	Excess (\$)		0.00	
	Assign From	HENG XINYI (SEAH ONG)	Assign Date		10/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model	KAWASAKI KR150K	c.c		150	
	Engine No.	HIDDEN	Year of Reg.		2003	
	Chassis No.	KR150KA57234	Colour		BLACK	
	Odometer	-	Steering		DISLODGED	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	90/90-17	MAXXIS		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	100/80-17	MAXXIS		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION AND O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/09/2020	Inspection Date	•	13/07/2021	
	Survey held at	ey held at LKT GROUP PTE LTD				
		3006 UBI ROAD 1 #01-384 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				