	Services (red i Done b		
DateIn 16/03 2023	Job description	Tane &Time Comple	i Dente to		
Retno NAI (7123002742 / d4	SAS e-filing		1		
VehNo PC8108R	E-mail (within 8las, APC 2	hrs,			
DOA 161.03 2023 09:00	i-Motor Claim Form				
160	i-Motor W/O (Within:	DD This, TP 4hrs)	·		
OD/TP/ Reporting Only	i-Photo Uploaded	:			
TP Insurer:	Assessment/Survey Re				
Tr institct.	Ass't Report by Fax / Hand to Owner/Wksp				
Preferred Wksp / INC Assign Wksp / QW: (Tel:	Fax:		
TP Particulars: Veh No: SG	5184H · · ·	NC()/Non-INC(1		
Owner / Driver: (Tel:) Cover Type: (
	riod: ()		
Confirmed by : (V: 0-20%; P: 21-79%. F	: 80-100%]		
	Warranty: YES ()/NO				
1 cm of registration (00()/\$2,000()				
General Remarks;-	The control of the second				
() Walk-In Customer: Customer's infor	rmation strictly Confidentia	al & Strictly NO refer of rep	alrer.		
() Total Loss Case : to e-mail Insure					
Drive-In () / Towed-In (); Invoice	: YES () / NO (); Towing Co. ()	
Remarks:- (1NC horline: 6788 6616)		Date&Time Comple	e'cd Done	.by	
1 1) Apply for Transitort Allowance ()/C	Courtesy Car ()				
Apply for Transport Allowance ()/C QC Check / Post Repair Inspection	Courtesy Car ()				
1) / (/) 101 112110 / / /	()				
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3	()				
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()	· · · · · · · · · · · · · · · · · · ·			
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()	Harris November (1911) AND STATE			
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()	· · · · · · · · · · · · · · · · · · ·			
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()	· · · · · · · · · · · · · · · · · · ·			
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()	· · · · · · · · · · · · · · · · · · ·			
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	() 3000] ()		Anit (S)	Am	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	() 3000] ()	ce Preparation Checklist	2.2 1 2 1 2 Anit (5)	Am	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions NA2300774	() 3000] () 4.000] () 5.000] () 1.000] ()	cc Preparation Checklist Accident Reporting (\$30); Damage Assessment (\$100);	Anit (S) (st Bill) INC (\$80)	1000000 mg/s	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time: Actions NA2300774 Claimant's Particulars	() 3000] () 4000] () 50	cc Preparation Checklist Accident Reporting (\$30); Damage Assessment (\$100); Towing Fee Follow-Through Survey	Anic (\$) Ist Bill INC (\$80) \$40/\$45 \$120	1000000 mg/s	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions NA2300774 Claimant's Particulars Driver/Owner:	() 3000] () 4nv0 1) AR: 2) DA 3) TF: 4) FT:	ce Preparation Checklist Accident Reporting (\$30); Darnage Assessment (\$100); Towing Fee Follow-Through Survey Follow-Through Survey (Resurve)	INC (\$80) \$40/\$45 \$120 () \$30	1000000 mg/s	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions NA2300774 Claimant's Particulars Driver/Owner: Contact No:	() 3000] () 3000] () 4000] () 1) AR: 2) DA 3) TF: 4) FT: 5) FT: For. 6) TR	ce Preparation Checklist Accident Reporting (\$30); Damage Assessment (\$100); Towing Fee Follow-Through Survey Follow-Through Survey (Resurve) Claiming against INC Only (wef 10) Re-inspection	INC (\$80) \$40/\$45 \$120 () \$30 Dan 2005) \$75	1000000 mg/s	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions NA2300774 Claimant's Particulars Driver/Owner:	() 3000] () 3000] () 4nyo 2) DA 3) TF: 4) FT: 5) FT: For. 6) TR 7) N1 8) NT	Cc Proparation Checklist Accident Reporting (\$30); Damage Assessment (\$100); Towing Fee Follow-Through Survey Follow-Through Survey (Resurve) Claiming against INC Only (wef 10) Re-inspection Idae DA + SMRT Survey JC Additional Services:-	INC (\$80) \$40/\$45 \$120 () \$30 Dan 2005)	1000000 mg/s	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions NA2300774 Claimant's Particulars Driver/Owner: Contact No: Damaged Portion:	() 3000] () 3000] () 4000] () 1) AR: 2) DA 3) TF: 4) FT: 5) FT: 6) TR 7) NI 8) NT: 9) NT:	cc Preparation Checklist Accident Reporting (\$30); Damage Assessment (\$100); Towing Fee Follow-Through Survey Follow-Through Survey (Resurve) Claiming against INC Only (wef 10); Re-inspection Idae DA + SMRT Survey UC Additional Services: Courtesy Car / Tpt Allowance	INC (\$80) \$40/\$45 \$120 () \$30 Dan 2005) \$75 \$160	1000000 mg/s	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions NA2300774 Claimant's Particulars Driver/Owner: Contact No:	() 3000] () 3000] () 31000] () 41000] () 510000] () 51000] () 51000] () 51000] () 51000] () 51000] () 51000] () 51000] () 51000] () 510000] () 51000] () 51000] () 51000] () 51000] () 51000] () 51000] () 51000] () 51000]	ce Preparation Checklist Accident Reporting (\$30); Damage Assessment (\$100); Towing Fee Follow-Through Survey Follow-Through Survey (Resurvey claiming against INC Only (wef 10) Re-inspection Idae DA + SMRT Survey JC Additional Services: : Courtesy Car / Tpt Allowance : Repair Co-ordination : Post Repair Inspection	INC (\$80) \$40/\$45 \$120 () \$30 Dan 2005) \$150 \$55 \$100 \$25	1000000 mg/s	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Dafe/Time Actions NA2300774 Claimant's Particulars Driver/Owner: Contact No: Damaged Portion: QC Checked by (Engr-In-Charge):	() 3000] () 3000] () 31000] 1) AR: 2) DA 3) TF: 4) FT: 5) FT: For. 6) TR 7) NI 8) NTO 900 * NS	ce Preparation Checklist Accident Reporting (\$30); Damage Assessment (\$100); Towing Fee Follow-Through Survey Follow-Through Survey (Resurve) claiming against INC Only (wef 10) Re-inspection Idae DA + SMRT Survey JC Additional Services: : Courtesy Car / Tpt Allowance : Repair Co-ordination : Post Repair Inspection : DV / Collect Excess Coordination	INC (\$80) \$40/\$45 \$120 () \$30) Jan 2005) \$75 \$160 \$25 \$100 \$25 \$35	1000000 mg/s	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions NA2300774 Claimant's Particulars Driver/Owner: Contact No: Damaged Portion: QC Checked by (Engr-In-Charge):	() 3000] () 3000] () 3000] () 4000] 3000] 3000] 4000]	cc Preparation Checklist Accident Reporting (\$30); Damage Assessment (\$100); Towing Fee Follow-Through Survey Follow-Through Survey (Resurve) Claiming against INC Only (wef 10) Re-inspection Idae DA + SMRT Survey JC Additional Services: Courtesy Car / Tpt Allowance Repair Co-ordination Fost Repair Inspection DV / Collect Excess Coordination (N11): TP (Non INC) against INC Idae Nobile	INC (\$80) \$40/\$45 \$120 () \$30) Jan 2005) \$75 \$160 \$25 \$100 \$25 \$35	1000000 mg/s	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving
- and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

16/03/2023 15:05 (SGT) Reported by Driver Date of Accident 16/03/2023 09:00 (SGT) Exact Location of Accident Singapore Additional Location Information **FULLERTON ROAD** Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Mercedes

Vehicle Registration Number PC8108R

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner LC LIMOUSINE SERVICES Company Reg No 5XXXX076M Email Address cklee8108@gmail.com Mobile Phone No (Phone) +65-96390676 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Model VITO115E EU4 Variant Exact purpose for which vehicle was being used at time of Employment accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Commercial vehicle Transmission Auto 2148

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Policy Number / Cover Note Number DMB1SNW00011472203

DRIVER

Name of Driver LEE CHENG KEE SXXXX313Z Date Of Birth 19/05/1959 Occupation Outdoor

Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	13/04/1978 44 YEARS AND 11 MONTHS Male (Phone) +65-96390676 cklee8108@gmail.com APT BLK 219 LORONG 8 TOA PAYOH # 07-641 310219 No Employee No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Side Swipe Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement	No 2 No - Yes 1 No
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?	No No
CIRCUMSTANCES OF ACCIDENT	
PLEASE REFER TO THE ATTACHED STATEMENT	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera?	Yes No R VEHICLE PROPERTY 1
Vehicle Registration Number Vehicle Manufacturer	SG5184H -
Vehicle Model	
Vehicle Variant	*
Vehicle Colour Vehicle Category	- Pura
Name of Driver	Bus WANG TAO
Work Permit No	0XXXX5061

Contact Number	(Phone) +65-92450013
Address	-
Address complement	_
Postcode	_
Insurance Company Name	-
Nature Of Damage	_
Details of property damaged in accident	1000 1000
No. Of Passenger (Including Driver)	-
110. Of 1 dooding of (moldaling office)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SG5033K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	_
Vehicle Colour	8=
Vehicle Category	Bus
Name of Driver	
Contact Number	-
Address	7 <u>2</u> 7
Address complement	-
Postcode	_
Insurance Company Name	_
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTALIT NOTICE

- Pleas report correctly the details of the accident to speed up the claims process.
- This = must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow
- 4. The is see and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any blse reporting may be referred to the Traffic Police Department for investigation.
- This reprised by the insurers to the GIA Records Management Centre established by the General Insurance Association of Sing pre (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the indgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
- 8. Consertunder the Personal Data Protection Act (PDPA)

Lunderstams, acknowledge, agree and consent that:

- (a) My line LPT, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administ eing my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of tertain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v), complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including the ir lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by (Name as in IRIC/ID card)

ketch Plan Fullerton Road PC 8108 R S45184H 5450334

on the above started date and time. I was driving along Fullerton Road and there was a bus stop on my left hand side. At the was behind bus SG 5033 k was startionary and vehicle B lashed out and hit the rear left side of my vehicle.	В
THE STORE OF MY VENICLE.	
Declaration We declar the pregging position	

oing particulars are true in every respect.

(ac 16/2/2)

Actual Driver's Signature (if driver is not the project older)

Witnessed by Reporting Centre Personnel
(Name of NRIC/ID card)

ACCIDENT STATEMENT

ACCIDENT DATE 16 103 2023 (DD/MM/YYYY), TIME 09 : 00 (HH:MM)	
LOCATION: Fullerton Road	
7. DETAILS OF VEHICLE	
DIVEHICLE NUMBER: PC8108R	
DINSURANCE COMPANY: China Taiping	
CICKNIMB P. IN R 7 SNUMBER OF THE PROPERTY OF	
A COLOR TITLE TO TAKE THE TENER OF THE TENER	
TITYPE (SALDON COURT) / MANUAL	
G) VEHICLE CATEGORY IPPIVATE (CO)	
b) PURPOSE OF HISTORY AND AND AND TORCYCLE)	
IF NO. PLEASE STATE THERE IS NOT OWN INSURANCE (YES/NO)	
2. INSURED / POLICY HOLDER	
A) NAME: LC Limousine Services b) NRIC/FIN/BASSPORT: 53285076M CONTACT: 9639067	
CIADDRESS: CONTACT: 9639 067	6
₩ 1.3% p. Persida Driver Driver ALSO POLICY HOLDER	8
Charles a ribbatter los characters	٠
(01) b) NRIC/FIN/PASSPORT: \$13.863/37 MALE/ FEMALE	
(01) DINRIC/FIN/PASSPORT: S1386313Z CONTACT: 9639 0671 CIADDRESS: APT BIK 219 Forong & Ton Payor # 07-641	0
. d) DATE OF BIRTH: (19 7 05 / 1959 1000 11)	
SYEARSTOF DRIVING EXPENSION IN 1879	
. WAS LIGHTER AN EMPLOYEE OF THE	
5. GIWEATHER CONDITION OF THE WITH INSURED	~
DIROAD SURFACE (DRY) WELL ARRIVED OTHERS	1
7. DIREPORTED TO POLICE MES CHO	4
18 LES, PLEASE STATE WHICH POUCE STATION-	
PARAMET OF VEHICLE NUMBER. SG SIRAL	15
relations driver DI DRIVER'S NAME Wand Tan	
() NRIC/FIN/PASSPORT: 077 168061 CONTACT: 9245 001	3
Lu LE PRECENARE O) VEHICLE NUMBER:	
oluding driver) DRIVER'S NAME MODEL: (CONTACT:	No
() NRIC/FIN/PASSPORT: CONTACT:	
	r

Cinari = Cklee 8108@gmeil, com



CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.



Motor Bus

MZ601

SN R

AN0681A

Cov. Type:F

CERTIFICATE OF INSURANCE

otor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.

DMB1SNW00011472203

Engine No.: 64698051487176

1. Index Mark and Registration

Cha. No.:WDF63970523394360

PC8108R

Number of Vehicle

2. Name of Policy Holder

LC LIMOUSINE SERVICES

Excess Sect. II

S\$1,500.00

Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment

26/07/2022 (00:00:00)

4. Date of Expiry of Insurance

25/07/2023

Persons or Classes of Persons entitled to drive*

Any person provided he is in the Policyholder's employ and is driving on their order or with their Any person provided ne is in the Policyholder's employ and is driving on their order or with their permission or any person driving with policyholder's permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use:*

Use only for the carriage of passengers or goods in connection with the Policyholder's business as specified in the Schedule.

The Policy does not cover

(1) Use for racing, pace-making, reliability trial or speed-testing.
(2) Use whilst drawing a trailer, except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

HIRE PURCHASE CO.: TAI THONG LEE TDG (PTE) LTD AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: MULTISYS AGENCIES & SERVICES

Authorised Officer

Authorised Signatory

China Taiping Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200208384E) 3 Anson Road #16-00 Springleaf Tower Singapore 079909

O6389 6111

6222 1033

www.sg.cntaiping.com