

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 17/02/2023 16:22 (SGT)
Reported by Both Policyholder and Actual Driver
Date of Accident 17/02/2023 14:10 (SGT)
Exact Location of Accident Loyang Avenue & Pasir Ris Drive 3, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SBS6494U

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Go Ahead Singapore Pte Ltd
Company Reg No 201541900C
Email Address claimsmatter@go-aheadsingapore.com
Mobile Phone No (Phone) +65-63847169
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Mercedes
Model Citaro
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Reporting only
Vehicle Category Bus
Transmission Auto
CC 6400

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd
Policy Number / Cover Note Number D-22099843MFBP

DRIVER

Name of Driver Siew Ah Lin
NRIC No S2699878F
Date Of Birth 04/06/1959
Occupation Outdoor

Date Of Driving Pass	31/08/1995
Driving experience	27 YEARS AND 6 MONTHS
Gender	Female
Mobile Number	(Phone) +65-94468368
Alt. Phone Number	-
Email Address	claimsmatter@go-aheadsingapore.com
Address	212 Tampines Street 23
Address complement	#04-127
Postcode	521212
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Siew Ah Lin was driving service 359 [SBS6494U] on the above-mentioned date & time. Whilst heading towards 98101 • Loyang Pt along Pasir Ris Dr 3 via Loyang Ave, SBS6494U's rear right anti-collision sensor dislodged after side sweeping against a stationary white Mitsubishi lorry [YN1868L] on the adjacent lane

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	DIFFERENT FORMAT

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN1868L
Vehicle Manufacturer	Mitsubishi
Vehicle Model	Fm65fm1rdea
Vehicle Variant	-
Vehicle Colour	White

Vehicle Category	Commercial vehicle
Name of Driver	Poobalan A/L Balasivam
Work Permit No	G8083478R
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-





