

ASS. REC. BY:

REF:

AIS/23002769/K

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Data/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Data/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S - RS. \$

Fees

Others

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP CLAIMSVehicle No. : SMD7532KMake & Model : VOLKSWAGEN PASSAT 1.8Year of Manufacture : 2018Chassis No. : WVWZZZ3CZJE221738Ins Company : ALLIANZEngine No. : CJS285014

Excess : _____

Policy No. : _____

Date of Accident : 07/03/2023Time of Accident : 07.20AM

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ 7,438.00Plus/Less 10% \$ 743.80Total of Cost / List \$ 6,694.20(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 6,694.20Labour (Appendix B) \$ 2,400.00Total Repair Cost \$ 9,094.20

Contact No

Frt Counter OperationBrenda Tel: 63837730 email: brendang@sparkcarcare.com
Rohani tel: 63837890 email: rohanim@sparkcarcare.com**Back-end Operation**Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com
Patrick Tel: 63837441 email: patricktia@sparkcarcare.com

Not Authorized
11 Days @
Recovery After Paint

The above total will be subjected to 8% G.S.T.

Name of Surveyor : KennethCompany : CKCSurvey conducted on : 23/3/23 at _____Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 23/3/23

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SMD7532K Case Owner : 0

Make & Model : VOLKSWAGEN PASSAT 1.8 Year Manufacture : 2018

Chassis No : WVWZZZ3CZJE221738 Engine No : CJS285014

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP CLAIMS

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyo
1	RR BUMPER	1	Ry	\$ 1,150.00			✓
2	RR BUMPER RETAINER LH	1	Ru	\$ 63.00			X
3	RR BUMPER RETAINER RH	1	Ru	\$ 63.00			X
4	RR BUMPER CLIP	10	Ru	\$ 90.00			✓
5	RR BUMPER REFLECTOR LH	1	CM	\$ 58.00			✓
6	RR BUMPER LOWER CHROME GARNISH	1	CM	\$ 215.00			✓
7	REVERSE SENSOR	2	Ju	\$ 350.00			X
8	RR BUMPER REINFORCEMENT	1	R	\$ 780.00			X
9	RR END PANEL	1	R	\$ 1,420.00			X
10	RR REINFORCEMENT BRACKET UPP LH/RH	2	nn				
11	RR REINFORCEMENT BRACKET LOW LH/RH	2	nn				
12	RR FENDER AIR DUCT LH	1	Ru	\$ 69.00			X
13	TAILLAMP LH	1	R	\$ 540.00			X
14	TAILGATE	1	R	\$ 2,150.00			X
15	TAILGATE LAMP LH	1	R	\$ 490.00			X
16	0	1					
17	0	1					
18	0	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	1					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No. : SMD7532K Case Owner : 0
Make & Model : VOLKSWAGEN PASSAT 1.8 Year of Manufacture : 2018

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.