

(08/13/13) wof

ASS. REC. BY: Rane

REF:

CS/FCU23002782/Rvg3

1054

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SGN9229Sat Workshop m/s VOLKSWAGENof ALEXANDRA RDInsured: XD 5618E FCU

Policy No.

Claims No. D23000943MFCV

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

0930

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

87K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 57K

5/4/23

Final fig \$4454.75 confirmed by email (red 5155.42, 53%)

Veh No:

SGN9229S

Yr Regn: 2018 / DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLKSWAGEN GOLF 1.4 TSI CL c.c 1395

Colour

RED

A/C: Insured / Std / NI / NA

Sp. Reading

54681

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZAUZKW035529

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

15/03/23

D.O.I.

21/03/23

Survey held at

VOLKSWAGEN

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair: 3

Resurvey No. of Trip: 1

1)

Date/Time, File Return to?

☐

: Final Report

2) 5/4/23-typist

Report Format: TP

Lump Sum / I.B.I. (\$) 4454.75

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details
Mr
GOH
YICK PHENG
BLK 142 BURGER ROAD STREET 11
#12-05
Singapore 050142

Document no.
Document date 16-03-2023
Customer no. 5211041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2023007472/ 1
Job order date 16-03-2023
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SGN9229S	BQ13HZ	31-12-2018	WVWZZZAUZKW035529	Golf 1.4 CLBM 92 TSI D7F	51,821

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
5G0807217FN GRU	Cover For Bumper Primed <i>de</i>	1	pcs.	1,452.18	#6	1,452.18	1,568.35
5G0919493L	Sensor Bracket	1	pcs.	15.49	#6	15.49	16.73
5G0919494G	Sensor Bracket	1	pcs.	15.49	#6	15.49	16.73
5G0919493J	Sensor Bracket	2	pcs.	14.85	#6	29.70	32.08
5Q0919133 9B9	Seal Ring Satin Black <i>new</i>	1	pcs.	1.53	#6	1.53	1.65
5Q0919275B GRU	Sensor Primed <i>new</i>	1	pcs.	194.63	#6	194.63	210.20
D 180KU2A1	2k-Plastic Adhesive <i>new</i>	1	pcs.	84.64	#6	84.64	91.41
D 822150A1	Bonding Agent For Plastic <i>new</i>	1	pcs.	74.37	#6	74.37	80.32
5G0807248G	Foam Insert <i>nn</i>	1	pcs.	73.70	#6	73.70	79.60
5G0807109AL	Impact Beam REINFORCEMENT <i>nn</i>	1	pcs.	835.24	#6	835.24	902.06
5G0807049B	Guide Piece BUMPER SIDE BRACKET LH <i>nn</i>	1	pcs.	37.13	#6	37.13	40.10
5G0807050B	Guide Piece BUMPER SIDE BRACKET RH <i>nn</i>	1	pcs.	37.13	#6	37.13	40.10
5G0805705R	Guide BUMPER CTR BRACKET <i>nn</i>	1	pcs.	85.41	#6	85.41	92.24
5G0853651CCZLL	Radiator Grille Satin Bla <i>nn</i>	1	pcs.	528.92	#6	528.92	571.23
3G0853601B DPJ	Vw Sign Black/Bright Chro <i>sea</i>	1	pcs.	106.72	#6	106.72	115.26
5G0853671G RYP	Cooling Air Grill Satin B BUMPER CTR BRACKET <i>nn</i>	1	pcs.	277.89	#6	277.89	300.12
	LABOUR	21	pcs.	840.00	#6	840.00	2,721.60
	SPRAY PAINT	21	pcs.	800.00	#6	800.00	2,592.00
	FRT NUMBER PLATE <i>4</i>	1	pcs.	80.00	#6	80.00	86.40
	INCOME ANY WS VS MS FIRST CAPITAL 3RD PARTY VEHICLE XD5618E D.O.A: 15-03-2023 SURVEY BY:						

Quotation valid till 23-03-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	8,850.17	8%	768.81	9,610.17	10,378.98
Total	760.00	8,850.17		768.81	9,610.17	10,378.98

*Payable
By 90010068
3 days
21/03/23 @ 0935*

Resum

*before
paint*

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details
Mr
GOH
YICK PHENG
BLK 142 BURIT BATOX STREET 11
#12-05
Singapore 650142

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

16-03-2023
5211041856
195000106C
30001
2023007472/ 1
16-03-2023
YEN MEI WONG

License plate
SGN9229S

Model code
BQ13HZ

First registration
31-12-2018

VIN
WVWZZZAUZ1W035529

Model
Golf 1.4 CLBM 92 TSI D7F

Mileage
51,821

Customer



—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 105G

Vehicle Details

Vehicle No.: SGN9229S

Vehicle to be Exported: No

Intended Deregistration Date: 21 Mar 2023

Vehicle Make: VOLKSWAGEN

Vehicle Model: GOLF 1.4 TSI CL

Primary Colour: Red

Manufacturing Year: 2018

Engine No.: CZC998373

Chassis No.: WWWZZZAUZKW035529

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$19,900.00

Original Registration Date: 31 Dec 2018

First Registration Date: 31 Dec 2018

Transfer Count: 0

Actual ARF Paid: \$19,900.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Dec 2028

PARF Rebate Amount: \$14,925.00

Intended COE Rebate Details

COE Expiry Date: 30 Dec 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$25,501.00

COE Rebate Amount: \$14,724.00

Total Rebate Amount: \$29,649.00

Volkswagen Golf 1.4A TSI Comfortline

Overview

[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)

Price	\$87,800		
Depreciation 	\$13,480 /yr View models with similar depre	Reg Date	28-Dec-2018 (5yrs 9mths 6days COE left)
Mileage	73,000 km (17.3k /yr)	Manufactured 	2018
Road Tax 	\$624 /yr	Transmission	Auto
Dereg Value 	\$29,653 as of today (change)	OMV 	\$19,900
COE 	\$25,501	ARF 	\$19,900
Engine Cap	1,395 cc	Power	92.0 kW (123 bhp)
Curb Weight 	1,270 kg	No. of Owners 	1
Type of Vehicle	Hatchback		