

(08/13/13) wof

ASS. REC. BY: Rane

REF:

CS/FCU23002782/Rvg3

1054

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SGN9229Sat Workshop m/s VOLKSWAGENof ALEXANDRA RDInsured: FCU

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

0930

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 87K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGN9229S Yr Regn: 2018 / DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLKSWAGEN GOLF 1.4 TSI CL c.c 1395Colour: RED A/C: Insured / Std / NI / NASp. Reading: 54681 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZAUZKW035529Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NII / S/Rim / STD A/Rim orTyre Size: F: 225/45R17R: 1BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 15/03/23

Survey held at

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 21/03/23Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 57K

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Document no.

Document date

16-03-2023

Customer no.

5211041856

Customer GST-ID

195000106C

Dealer

30001

Job order number

2023007472/ 1

Job order date

16-03-2023

Service Advisor

YEN MEI WONG

Company

Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details

Mr
GOH
YICK PHENG
BLK 142 BUKIT BATOK STREET 11
#12-05
Singapore 650142

License plate

SGN9229S

Model code

BQ13HZ

First registration

31-12-2018

VIN

WVWZZZAUZKW035529

Model

Golf 1.4 CLBM 92 TSI D7F

Mileage

51,821

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
5G0807217FNGRU	Cover For Bumper Primed <i>de</i>	1	pcs.	1,452.18	#6	1,452.18	1,568.35
5G0919493L	Sensor Bracket	1	pcs.	15.49	#6	15.49	16.73
5G0919494G	Sensor Bracket	1	pcs.	15.49	#6	15.49	16.73
5G0919493J	Sensor Bracket	2	pcs.	14.85	#6	29.70	32.08
5Q0919133 9B9	Seal Ring Satin Black <i>new</i>	1	pcs.	1.53	#6	1.53	1.65
5Q0919275B GRU	Sensor Primed <i>new</i>	1	pcs.	194.63	#6	194.63	210.20
D 180KU2A1	2k-Plastic Adhesive <i>new</i>	1	pcs.	84.64	#6	84.64	91.41
D 822150A1	Bonding Agent For Plastic <i>new</i>	1	pcs.	74.37	#6	74.37	80.32
5G0807248G	Foam Insert	1	pcs.	73.70	#6	73.70	79.60
5G0807109AL	Impact Beam	1	pcs.	835.24	#6	835.24	902.06
	REINFORCEMENT						
5G0807049B	Guide Piece	1	pcs.	37.13	#6	37.13	40.10
	BUMPER SIDE BRACKET LH						
5G0807050B	Guide Piece	1	pcs.	37.13	#6	37.13	40.10
	BUMPER SIDE BRACKET RH						
5G0805705R	Guide	1	pcs.	85.41	#6	85.41	92.24
	BUMPER CTR BRACKET						
5G0853651CCZLL	Radiator Grille Satin Bla	1	pcs.	528.92	#6	528.92	571.23
3G0853601B DPJ	Vw Sign Black/Bright Chro	1	pcs.	106.72	#6	106.72	115.26
5G0853671G RYP	Cooling Air Grill Satin B	1	pcs.	277.89	#6	277.89	300.12
	BUMPER CTR BRACKET						
	LABOUR	21	pcs.	840.00	#6	840.00	2,721.60
	SPRAY PAINT	21	pcs.	800.00	#6	800.00	2,592.00
	FRT NUMBER PLATE	1	pcs.	80.00	#6	80.00	86.40
	INCOME ANY WS VS MS FIRST CAPITAL						
	3RD PARTY VEHICLE XD5618E						
	D.O.A: 15-03-2023						
	SURVEY BY:						

Quotation valid till 23-03-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	8,850.17	8%	768.81	9,610.17	10,378.98
Total	760.00	8,850.17		768.81	9,610.17	10,378.98

Payable
By 90010068
3 days

21/03/23 @ 0935

Resum

before paint

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
GOH
YICK PHENG
BLK 142 BURIT BATOK STREET 11
#12-05
Singapore 650142

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

16-03-2023
5211041856
195000106C
30001
2023007472/ 1
16-03-2023
YEN MEI WONG

License plate
SGN9229S

Model code
BQ13HZ

First registration
31-12-2018

VIN
WVWZZZAUZ1W035529

Model
Golf 1.4 CLBM 92 TSI D7F

Mileage
51,821

Customer



—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 105G

Vehicle Details

Vehicle No.: SGN9229S

Vehicle to be Exported: No

Intended Deregistration Date: 21 Mar 2023

Vehicle Make: VOLKSWAGEN

Vehicle Model: GOLF 1.4 TSI CL

Primary Colour: Red

Manufacturing Year: 2018

Engine No.: CZC998373

Chassis No.: WWWZZZAUZKW035529

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$19,900.00

Original Registration Date: 31 Dec 2018

First Registration Date: 31 Dec 2018

Transfer Count: 0

Actual ARF Paid: \$19,900.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Dec 2028

PARF Rebate Amount: \$14,925.00

Intended COE Rebate Details

COE Expiry Date: 30 Dec 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$25,501.00

COE Rebate Amount: \$14,724.00

Total Rebate Amount: \$29,649.00

Volkswagen Golf 1.4A TSI Comfortline

Overview

[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)

Price	\$87,800		
Depreciation 	\$13,480 /yr View models with similar depre	Reg Date	28-Dec-2018 (5yrs 9mths 6days COE left)
Mileage	73,000 km (17.3k /yr)	Manufactured 	2018
Road Tax 	\$624 /yr	Transmission	Auto
Dereg Value 	\$29,653 as of today (change)	OMV 	\$19,900
COE 	\$25,501	ARF 	\$19,900
Engine Cap	1,395 cc	Power	92.0 kW (123 bhp)
Curb Weight 	1,270 kg	No. of Owners 	1
Type of Vehicle	Hatchback		