



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI23002790/Avy3e2

Date: 08/06/2023

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 5320A	Veh. Inspected	GBD 1640B
Policy No.	P10563321R01	Coverage (\$)	0.00
Claim No.	C10021106 /CD	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	17/03/2023

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VM20055422	Colour	WHITE
Odometer	260474 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14C	GOODYEAR	6 mm
L/H Front Tyre	175/70 R14C	GOODYEAR	6 mm
R/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm
L/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/03/2023	Inspection Date	17/03/2023
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
--	------------------------