

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI23002791/Kwy3q2	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	: 18/05/2023	
			Code	e: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNB 3888J	Veh. Inspected	SMJ 1223K	
	Policy No.	P10840829R00	Coverage (\$)	0.00	
	Claim No.	C10021102 /CH	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	17/03/2023	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ A200 (A)	c.c	1332	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	WDD1770872J020108	Colour	METALLIC BLACK	
	Odometer	39273 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R18	GOODYEAR	8 mm	
	L/H Front Tyre	225/45 R18	GOODYEAR	8 mm	
	R/H Rear Tyre	225/45 R18	GOODYEAR	8 mm	
	L/H Rear Tyre	225/45 R18	GOODYEAR	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	15/03/2023	Inspection Date	20/03/2023	
	Survey held at	THIAM HENG HUAT PTE LTD	•		
		176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: