

 Service Request Details

Claim	S3M04KKG
Reference	CS3/HSB23002801/Wnp3m4 
Loss Date	15 March 2023
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	17 Mar 2023 10:10:45 AM
Request Date	17 March 2023
Due Date	

Actions

Next Step Add invoice

Add Invoice

Vehicle Information

Incident GBC6806M
Vehicle
Registration #

Make TPVD

Model NISSAN

Service Address

, , ,

Primary Contact/Insured

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

LOH Cynthia

cynthia.loh@axa.com.sg

Additional Instructions

Messages2InvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 HSB-LKKInvoice-AC2301990.pdf.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2023
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2023
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2023
 GBC 6806M-AXA Immediate Advice (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 March 2023
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	17 March 2023
 TP GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	17 March 2023
 SHD4904A INS GIA.pdf.pdf	Reports &	GIA Report	KUMAR Shailendra	17 March

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
	Statement			2023
 PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	17 March 2023
 PRI TP PDF.pdf.pdf	Legal	Others	KUMAR Shailendra	17 March 2023