

REF:

From: _____ Date: _____

Veh No: SL254442 Yr Regn: 2018 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3- C.C. 1496

Colour Grey A/C: Insured / Std / NI / NA

Sp. Reading 158759. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BX22A8H0164600.

Gen. Cond. Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

RS / DIIN / EXNOVA / GY / ES / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO of CGP Sen

Front Rear

R/Bal.	01	mm	R/Bal.	06	mm
--------	----	----	--------	----	----

L/Bal. 05 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 20/03/23.

Survey held at Al

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Report Format

Add Fee: : Site Insp (\$

1: Interview (\$

1: Tech. (page 1)

Survey Fee:

Transportation:

$$S + RS, \quad SI$$

Photos

Others