

ASS. REC. BY:

REF:

C12 / 23 002846 / Kps.

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMS 5003E Yr Regn: 12, 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Maruti Suzuki XE 1999Colour: M. D. Blue A/C: Insured / Std / NI / NASp. Reading: 107233 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SATA B4 AG3 HA 967908Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: _____

R: 245/40ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 17/3/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/3 21 Rm @ 4600h Cntr @ 04 days (Red \$3,605.50/44%)

Date/Time, File Pass to?

☐ : Prel. Report☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format: TP

Lump Sum / I.B.I. (\$) 4/5 \$4600

TOTAL

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **China Taiping Insurance (Singapore) Pte. Ltd**
3, Anson Road,
#16-00, Springleaf Tower,
Singapore 079909

Attn : Motor Claims Department
Tel : 6389 6111
Fax : 6222 1033

Estimate bill : TT 18 / 23 / TP / WT

Registration No : SMS5003E

Make / model : Jaguar XE 2.0
Turbo

Mileage :

Date : 20 / 03 / 2023

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: GBJ5287E AND SMS5003E ALONG
11 WOODLANDS CI, SINGAPORE 737854 ON 17 MARCH 2023 AT ABOUT 0830HRS.

1pc	Rear boot	2056.70	Part/wrap	\$	2,112.00	X
1pc	Rear boot emblem with 'Jaguar' designation	142		\$	267.00	X
1pc	Rear boot 'XE' designation	80		\$	127.00	X
1pc	Rear boot '2.0' designation	80		\$	151.00	X
1pc	Rear bumper		Buy 1 pc	\$	1,774.00	X
2 pcs	Rear bumper parktronic sensor		(Each \$157.00)	\$	628.00	X
1pc	Rear bumper towing cover		(Each \$54.00)	\$	59.00	X
1pc	Rear bumper lip	786		\$	835.00	X
2pcs	Rear bumper side retainer		(Each \$174.00)	\$	348.00	X
1pc	Rear bumper frame (Centre)			\$	244.00	X
	Sub A total :			\$	6,545.00	
	Less 10% discount :			\$	654.50	
	A total :			\$	5,890.50	
Special net items :						
1pc	Rear license smart plate & casing			\$	35.00	X
	B total :			\$	35.00	

Remove and transfer rear boot necessary attachment part part items.

Remove and transfer rear bumper necessary attachment part part items.

Remove and refit rear boot, rear boot emblem with 'Jaguar' designation, rear boot 'XE' designation, rear boot '2.0' designation, rear bumper, rear bumper parking sensors, rear bumper towing cover, rear bumper lip, rear bumper side retainers, rear bumper frame.

Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

Diagnostic and reset rear bumper parktronic sensor fault error by HHT

Total amount of Page 1 :

\$ 900.00 4501
\$ 100.00 601
\$ 6,925.50

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **China Taiping Insurance (Singapore) Pte. Ltd**
3, Anson Road,
#16-00, Springleaf Tower,
Singapore 079909

Estimate bill : TT 18 / 23 / TP / WT

Registration No : SMS5003E

Attn : Motor Claims Department
Tel : 6389 6111
Fax : 6222 1033

Make / model : Jaguar XE 2.0
Turbo

Mileage :

Date : 20 / 03 / 2023

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: GBJ5287E AND SMS5003E ALONG
11 WOODLANDS CI, SINGAPORE 737854 ON 17 MARCH 2023 AT ABOUT 0830HRS.

To check and refit rear tail lamp wiring harness.	\$	80.00	200
Under coating on rear damaged portion.	\$	200.00	300
Putty / primer application, spray painting rear boot, rear bumper, rear bumper parking sensors, rear bumper towing cover.	\$	1,000.00	500
Balance amount brought from Page 1 :	\$	6,925.50	
Grand final amount :	\$	8,205.50	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/03/2023 12:28 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	17/03/2023 08:30 (SGT)
Exact Location of Accident	11 Woodlands Cl, Singapore 737854
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMS5003E
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	YEO SHAN YUAN
NRIC No	S8931107A
Email Address	SHANYUAN.YEO.68@GMAIL.COM
Mobile Phone No	(Phone) +65-84848108
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Jaguar
Model	Xe
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only
Vehicle Category	Private car
Transmission	Auto
CC	2000

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW00153022201

DRIVER

Name of Driver	YEO SHAN YUAN
NRIC No	S8931107A
Date Of Birth	07/09/1989
Occupation	Indoor

Date Of Driving Pass	07/06/2010
Driving experience	12 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-84848108
Alt. Phone Number	-
Email Address	SHANYUAN.YEO.68@GMAIL.COM
Address	BLK694C WOODLANDS DRIVE 62 #13-56
Address complement	-
Postcode	733694
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	LOW PEI QI
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

VEHICLE A IS PARKED STATIONARY IN PARKING LOT. VEHICLE B HIT VEHICLE A FROM BEHIND.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	WITH OWNER

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ5287E
Vehicle Manufacturer	-
Vehicle Model	-

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	LEE YONG KONG
Contact Number	(Phone) +65-93917224
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE B
No. Of Passenger (Including Driver)	-


SKETCH PLAN

IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claim process.
2. The form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) my insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information contained in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the sending of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law or administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

17/1/23
 Policyholder's Signature / Date & Time _____
 Driver's Signature (if Driver is not the policyholder) / Date & Time _____
 Witnessed by Reporting Centre Personnel _____

Sketch Plan



Describe Circumstances of the Accident

~~We were~~ Vehicle A is parked stationary in parking lot.
Vehicle B hit Vehicle A from behind.

Declaration

I/We declare the foregoing particulars are true in every respect.

 17/9/25
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

6807392



NRIC No. **S8931107A**



Date of Issue
03-03-2022

Address

**APT BLK 694C WOODLANDS DRIVE 62
#13-56
SINGAPORE 733694**

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8931107A



Name

YEO SHAN YUAN

Race

CHINESE

Date of birth

07-09-1989

Sex

M

Country/Place of birth

SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars =< 3000kg with =< 7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg **07 Jun 2010**



Licence No: S8931107A

NP 428A

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8931107A



YEO SHAN YUAN

Birth Date: 07 Sep 1989

Issue Date: 07 Jun 2010



001863709E



● 2019年12月10日

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	107A

Vehicle Details

Vehicle No.:	SMS5003E
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Mar 2023
Vehicle Make:	JAGUAR
Vehicle Model:	XE 2.0 I4P TSS
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	015324055758204PT
Chassis No.:	SAJAB4AG3HA967968
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$36,729.00
Original Registration Date:	23 Dec 2016
First Registration Date:	23 Dec 2016
Transfer Count:	1
Actual ARF Paid:	\$43,421.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2026
PARF Rebate Amount:	\$28,223.00

Intended COE Rebate Details

COE Expiry Date:	22 Dec 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,229.00
COE Rebate Amount:	\$17,398.00
Total Rebate Amount:	\$45,621.00

The information contained herein is correct as at 17 Mar 2023

OK