



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23002863/Uny3e2 Date: 19/04/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SNB 650Y	Veh. Inspected	SMU 992Y	
Policy No.	P10609520R01	Coverage (\$)	0.00	
Claim No.	C10021155 /SR	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	20/03/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	JAGUAR XJ 2.0 (A)	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	SAJAC12M3GPW01827	Colour	WHITE	
Odometer	120677 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/45Z R19	FALKEN	6 mm	
L/H Front Tyre	245/45Z R19	FALKEN	6 mm	
R/H Rear Tyre	245/45Z R19	FALKEN	6 mm	
L/H Rear Tyre	245/45Z R19	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/03/2023	Inspection Date	21/03/2023	
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	