

ASS. REC. BY:

REF:

AG/230029021kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STN 8767B

Yr Regn:

03, 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

C.C.

1598

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

166185

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR0538EE108139211

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

4

mm

Rear

R/Bal.

8

mm

L/Bal.

6

mm

L/Bal.

8

mm

D.O.A.

19/3/23

D.O.I.

21/3/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

F. 100%

Others

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

AUTOWROX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

BOON HOE

c/o 46 Lentor Plain
Singapore 786548

Not Authorised
1/1 Rpt &
Review After 1st Mtg
5 days

Date: 21/03/2023

| QUANTITY | PARTICULARS | AMOUNT (\$) |
|--------------------------------------|--|----------------------------------|
| RE: TOYOTA ALTIS / SJN 8767 B | | |
| 1 pc | rear boot lid | <i>Pl</i> 798.00 |
| 1 pc | rear boot chrome moulding | <i>Pl</i> 256.30 X |
| 2 pcs | rear boot lamp @ 435.40 | <i>Gr</i> 870.80 |
| 1 pc | rear boot emblem ' 1.6E ' | <i>Pl</i> 61.80 |
| 1 pc | rear boot emblem ' ALTIS ' | <i>Pl</i> 61.70 |
| 1 pc | rear boot emblem ' COROLLA ' | <i>Pl</i> 59.40 |
| 1 pc | rear boot emblem ' LOGO ' | <i>Pl</i> 71.80 |
| 1 pc | rear boot lock | <i>Pl</i> 197.50 |
| 1 pc | rear boot lock catch | <i>Pl</i> 65.30 X |
| 1 pc | rear boot lock remote actuator | 232.60 |
| 1 pc | rear boot weatherstrip | <i>Di/Pl</i> 380.70 <i>SE/Pl</i> |
| 2 pcs | rear boot hinge @ 292.40 | <i>Pl</i> 584.80 X |
| 1 pc | rear end panel | <i>Pl</i> 467.10 |
| 1 pc | rear end panel garnish | <i>mb Pl</i> 285.00 |
| 1 pc | rear bumper | <i>CMB</i> 592.90 |
| 2 pcs | rear bumper reflector <i>Al/sem</i> @ 126.40 | 252.80 |
| 1 pc | rear bumper foam w/ reinforcement bar | <i>CMB</i> 392.30 |
| 2 pcs | rear bumper side retainer @ 63.00 | <i>DIT</i> 126.00 |
| 2 pcs | rear bumper corner retainer @ 76.70 | <i>DIT</i> 153.40 |
| 2 pcs | rear tail lamp assy @ 487.60 | 975.20 |
| 1 pc | rear spare tyre top board | <i>Pl</i> 198.50 X |
| sub-total | | 7,083.90 |
| less 25% | | 1,770.98 |
| sub-total | | 5,312.93 |
| 1 pc | reverse camera s.nett | <i>Pl</i> 450.00 X |
| 1 pc | reverse sensor s.nett | <i>Pl</i> 220.00 <i>200w</i> |
| sub-total | | 5,982.93 |

Balance brought forward.

5,982.93

To remove and replace the parts mentioned above,
panel beat and realign the necessary affected areas.

600 1,200.00

To check wiring system.

200 40.00

To apply rust proofing on affected areas.

600 150.00

To apply waterproof sealant on affected areas.

300 150.00

To apply putty & spray painting on affected areas.

600 1,300.00

To install reverse sensors & reverse camera.

500 150.00

To remove carpet and trimming to enable repair.

600 100.00

To carry out exhaust works.

nn 80.00 X

Total

9,152.93

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|------------------------|
| Date of Submission | 20/03/2023 15:44 (SGT) |
| Reported by | Owner |
| Date of Accident | 19/03/2023 14:50 (SGT) |
| Exact Location of Accident | Mandai Rd, Singapore |
| Additional Location Information | - |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|------------------------|
| Vehicle Registration Number | SJN8767B |
| INSURED/POLICYHOLDER | |
| Is company? | Yes |
| Name Of Registered Owner | BOON HOE |
| Company Reg No | 5XXXX473E |
| Email Address | boonpin_91@hotmail.com |
| Mobile Phone No | (Phone) +65-98257628 |
| Alternative Phone No | - |

VEHICLE PARTICULARS

| | |
|--|---------------------------|
| Manufacturer | Toyota |
| Model | Corolla |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | - |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Private hire |
| Transmission | Auto |
| CC | 1598 |

INSURANCE COMPANY

| | |
|-----------------------------------|--------------------------|
| Name of Insurance Company | Income Insurance Limited |
| Policy Number / Cover Note Number | 5099947711-04 |

DRIVER

| | |
|----------------|--------------|
| Name of Driver | ANG BOON PIN |
| NRIC No | SXXXX132E |
| Date Of Birth | 20/05/1991 |
| Occupation | Indoor |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Boon Hoe

Co Reg No: 53356473E




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A: SJN 876TB

B: SMA 693R.