

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



		AUTOMOBILE INSI	LOTI	ON KLFOKI		
INCOME INSURANCE LTD R				NS/INC23002963/Sqp3m4		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	10-05-2023		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SNA 881C	Veh. Ir	nspected	SHB 3377M	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1216623-001	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	22/02/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	JTDKB3FU703089627	Colou	r	YELLOW	
	Odometer	207436	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65R15	WEST	LAKE	5 mm	
	L/H Front Tyre	195/65R15	WEST	LAKE	5 mm	
	R/H Rear Tyre	195/65R15	WEST	LAKE	5 mm	
	L/H Rear Tyre	195/65R15	WEST	LAKE	5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	17/02/2023	Inspec	tion Date	22/02/2023	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				