

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 22.02.2023

INSURANCE: INCOME (LKS)

MODEL: Toyota Prius G4A

MVA: LIM T S

VEHICLE NO.: SHB3377M

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper <i>Scr R</i>	1		\$591.75 <i>R</i>
	Front Bumper Clips <i>XNW</i>	10	\$2.20	\$22.00
	Front Bumper Bracket RH <i>XNW</i>	1		\$77.00
	Front Bumper Grille RH <i>?</i>	1		\$85.10 <i>XNW</i>
	Front Wheel Rim RH <i>Scr R</i>	1		\$1,570.55 <i>R</i>
	SUB TOTAL			\$2,346.40
	LESS 25%			\$586.60
	DISCOUNTED TOTAL			\$1,759.80
	Labour Charge			
	Panel Beating			\$400.00 <i>350</i>
	Spray Painting Charge			\$300.00 <i>250</i>
	Wheel Alignment			\$120.00 <i>40</i>
	TOTAL LABOUR			\$820.00
	ESTIMATE TOTAL			\$2,579.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

T=640 2 days LKS PIP

22/2/23 3pm

S/ Fan

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: