

ASS. REC. BY:

REF:

SMR/ 23002975/Kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SUL 2195C

Yr Regn:

02, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Seat

Alhambra C.C.

1968

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

115622

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VPS 888 7N24V 713325

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

16/3/23

D.O.I.

28/3/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Ching Motor Repair Shop

Blk 176 #02-08 Sin Ming Drive Sin Ming AutoCare
Singapore 575721 HP 91004390/91254449 Fax 6484 1482
Email : chingmotorrepair@gmail.com

M/s SMRT Automotive Services Pte Ltd DATE 28.03.2023
60 Woodlands Industrial Park E4 CAR NO SLL 2195 C
Singapore 757705 MAKE Seat/Alhambra 2.0

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SG 3013 G

Pc	Pcs	VSSZZZ7NZHV713325	UNIT PRICE	AMOUNT
1	pc	Front left side fender <i>At ✓</i>		
1	pc	Front left side fender cowling <i>Per X</i>		
1	pc	Front left side head lamp <i>my car ✓</i>		
1	pc	Front bumper <i>Bel/Not ✓</i>		
1	pc	Front bumper left hand side retainer <i>Dir ✓</i>		
		Labour for cutting front left side fender, disamentle and replace the above mentioned parts.		<i>400</i> \$1,000.00
		To respray front left side fender and front bumper.		<i>400</i> \$700.00
<i>NOT NOTHAWED</i> <i>1/1 Rmp &</i> <i>Rehany After Repair</i> <i>4 days</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____				
Page 1 of 1			Total	

Susan Lim

Ching Motor Repair Shop.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/03/2023 16:00 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	16/03/2023 17:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SENJA ROAD AND BUKIT PANJANG RING ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLL2195C

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN CHEW YEN
NRIC No	S8038397E
Email Address	kristie13@gmail.com
Mobile Phone No	(Phone) +65-97683595
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Seat
Model	ALHAMBRA
Variant	TDI DSG 2.0
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1968

INSURANCE COMPANY

Name of Insurance Company	Singapore Life Ltd
Policy Number / Cover Note Number	11412609


DRIVER

Name of Driver	TAN CHEW YEN
NRIC No	S8038397E
Date Of Birth	13/11/1980
Occupation	Indoor



ACCIDENT DIAGRAM

Ver. Jun2022



124
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Mohamed Saifulah S/O Syed Masood
Witnessed by Reporting Centre
Personnel