

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/196R GST Reg. No. 19-900/196-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	_ INSURANCE (S) PL	R	ef:	CS/AGI23002978/Kqy3m4	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	09/06/2023	
			C	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLA 9584A	Veh. Inspected		SLD 5595D	
	Policy No.	P10515594R01	Coverage (\$)		0.00	
	Claim No.	C10021184/JY	Excess (\$)		0.00	
	Assign From	FRAULEINE KHOO	Assign Date		22/03/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	RU11117734	Colour		METALLIC BLUE	
	Odometer	89065 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60R15	MICHELIN		8 mm	
	L/H Front Tyre	215/60R15	MICHELIN		8 mm	
	R/H Rear Tyre	215/60R15	MICHELIN		8 mm	
	L/H Rear Tyre	215/60R15	MICHELIN		8 mm	
4.		Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	20/03/2023	Inspection Date		23/03/2023	
	Survey held at	THIAM HENG HUAT PTE LTD				
		176 SIN MING DRIVE #05-14 SINGAPORE 575721				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: