

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERAL	L INSURANCE (S) PL	Ref	: CS/AGI23002981/Rqy3m4	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Dat	e: 20/06/2023	
			Cod	de: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMP 7995U	Veh. Inspected	SG 5906S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10021193/JL	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	22/03/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MAN A95	c.c	10518	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	WMAA95ZZ0HF003890	Colour	GREEN	
	Odometer	327353 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	275/70R22.5	GOODYEAR	8 mm	
	L/H Front Tyre	275/70R22.5	GOODYEAR	8 mm	
	R/H Rear Tyre	275/70R22.5 (D/D)	GOODYEAR	8/8 mm	
	L/H Rear Tyre	275/70R22.5 (D/D)	GOODYEAR	8/8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	02/03/2023	Inspection Date	22/03/2023	
	Survey held at 154 GUL CIRCLE SINGAPORE 629611				
	Repairer	Repairer BOXFRESH PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

1 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: