

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMD23002982/4943

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XD5-235at Workshop m/s 1.1's 120

of _____

Insured: YQ303R

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: \$43k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: Reg 812kVeh No: XD5235BYr Regn: 06/09/11Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover

Truck / Trailer or _____

Make: HIND SHIEERA132
c.c129/13Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 374772

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SHIEER10027Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 295-180 R22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Austone

Front

Rear

R/Bal. 6 mmR/Bal. 6/6 mmL/Bal. 6 mmL/Bal. 6/6 mmD.O.A. 17/3/23D.O.I. 22/3/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Co until 05-09-2026 LTA 1353229/3/23 1/5 @ 5200 inspect susen CRad \$4339.20, 45%

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 5200

ESTIMATE

Name: Sompo Insurance Singapore Private Limited

Ref Date:

22-03-2023

Address Motor Claims Department

Ref No:

XD5235B230317

50 Raffles Place #05-01 / 06

Vehicle No:

XD5235B

Singapore Land Tower Singapore 048623

Model / Make:

Hino SH1EERA

13L Manual ABS Turbo

[illegible]

Total Parts & Labour of estimate for damaged vehicle

\$ 9,539.20

Total amount in Lumpsum Basis for repaired vehicle	
1	2
3	4
5	6
7	8
9	10
11	12
13	14
15	16
17	18
19	20
21	22
23	24
25	26
27	28
29	30
31	32
33	34
35	36
37	38
39	40
41	42
43	44
45	46
47	48
49	50
51	52
53	54
55	56
57	58
59	60
61	62
63	64
65	66
67	68
69	70
71	72
73	74
75	76
77	78
79	80
81	82
83	84
85	86
87	88
89	90
91	92
93	94
95	96
97	98
99	100

\$ -

SDL



Liu's Bro Auto Engrg Wks

not full on
her
22/3/23
2/5 \$5200
the 1st day
5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

$$\begin{array}{r} 1-5461.86 \\ 102 \\ \hline 4915.67 \\ 1650 \\ \hline 6565.67 \\ 202 \\ \hline 6767.67 \end{array}$$

INSURER ENQUIRY

Find
insurer

Vehicle reg. no.

YQ303R

Date of Accident

17/03/2023 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance **Sompo Insurance Singapore P...**Period of Insurance **10/05/2022 - 30/09/2023**Requested By **Susan Low (Liu's Brother Auto...**Requested Date **22/03/2023 09:14****Payment details**Request Amount: **S\$1.85**GST Amount: **S\$0.15**Total Amount Due (GST Inclusive): **S\$2****General Insurance Association**

Records Management Centre

GST Registration No: **M400017735**

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 196N

Vehicle Details

Vehicle No.: XD5235B

Vehicle to be Exported: No

Intended Deregistration Date: 22 Mar 2023

Vehicle Make: HINO

Vehicle Model: SH1EERA 13L MANUAL ABS TURBO

Primary Colour: White

Manufacturing Year: 2011

Engine No.: E13CUN16031

Chassis No.: SH1EER10027

Maximum Power Output: -

Open Market Value: \$87,652.00

Original Registration Date: 06 Sep 2011

First Registration Date: 06 Sep 2011

Transfer Count: 1

Actual ARF Paid: \$4,383.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 05 Sep 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$19,586.00

COE Rebate Amount: \$13,532.00

Total Rebate Amount: \$13,532.00**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 22 Mar 2023

OK