(08/11/03) wef

ASS. REC. BY:

REF: C33/SMR22010204/Rqy3 -1

ASSIGNMENT

From : Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JGC 8885

at Workshop m/s MINH HWA AUTO SVC

of 160, SIN MING DR #02-16

Insured: SMR

Policy No.

Claim's No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 7K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: JGC 8885 Yr Regn: 2001 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: PROTON WIRA 1.5GL c.c 1468

Colour WHITE A/C: Insured / Std / NI / NA

Sp.Reading 130899 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PL1C97LKR1B596089

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	12/10/22	D.O.I.	18/10/22

Survey held at MINH HWA

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 7K

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (4K-5K) / 7 days

29/03/23 Submit LS $4400, 11 days. (Red $4700, 52%)

Date/Time, File Pass to? ☐ : Preli. Report

1) 29/03 Typist ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 11

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: S + RS SI

Photos

Others

TOTAL

Report Format : TP

Lump Sum ~~H.B.I.~~ ($ 4400)