

(08/13) wef

ASS REC. BY: Passive


REF: CS/CTI 2300 3024/RUP3

7269

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD: WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJJ 7799L
 at Workshop m/s: PERFORMANCE
 of: OLEXANDRA RD
 Insured: GY 247R CTI
 Policy No. DMCVSNA00002722302
 Ref No. SNM23D202011/C02/LEWLC
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJJ 7799L Yr Regn: 2022, Jun
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: B.M.W IX XDRAIVE 40SPS/R.c.c
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 06254 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBY12CF080CK51594
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / 8/Rim / STD A/Rim or
 Tyre Size: F: 275/40R22
 R: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Bal. or Market Value: 356k
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Turn Sum: % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 15/03/23 D.O.I. 30/05/23
 Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
REPAIR LIMIT - 175K

2/8/23 Final fig \$3867.60 confirmed by email (Red 3719.55, 49%)

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: _____

Date/Time, File Return to?
 2) 4/8/23-typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
 Transportation: _____
) S + RS, SI
) Photos
) Others
 TOTAL

Report Format : Merimen
 Lump Sum / I.B.I.: (\$ 3867.60)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|-------------------------------------|
| Date of Submission | 17/03/2023 13:53 (SGT) |
| Reported by | Both Policyholder and Actual Driver |
| Date of Accident | 15/03/2023 22:14 (SGT) |
| Exact Location of Accident | Singapore |
| Additional Location Information | MCE TOWARDS CHANGI AIRPORT |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJJ7799L

INSURED/POLICYHOLDER

| | |
|--------------------------|------------------------|
| Is company? | No |
| Name Of Registered Owner | ZHAO WEI |
| NRIC No | SXXXX726G |
| Email Address | zhaowei@singhai.com.sg |
| Mobile Phone No | (Phone) +65-98161723 |
| Alternative Phone No | - |

VEHICLE PARTICULARS

| | |
|--|----------------------------|
| Manufacturer | BMW |
| Model | IX XDRIVE40 SPORTS LED PGR |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Private car |
| Transmission | Auto |
| CC | 0 |

INSURANCE COMPANY

| | |
|-----------------------------------|---------------------------|
| Name of Insurance Company | Liberty Insurance Pte Ltd |
| Policy Number / Cover Note Number | - |

DRIVER

| | |
|----------------|------------|
| Name of Driver | ZHAO WEI |
| NRIC No | SXXXX726G |
| Date Of Birth | 01/09/1965 |
| Occupation | Indoor |

| | |
|--|------------------------|
| Date Of Driving Pass | 16/12/1999 |
| Driving experience | 23 YEARS AND 3 MONTHS |
| Gender | Male |
| Mobile Number | (Phone) +65-98161723 |
| Alt. Phone Number | - |
| Email Address | zhaowei@singhai.com.sg |
| Address | 88 SENNETT AVENUE |
| Address complement | - |
| Postcode | 467096 |
| Is the driver the policyholder? | Yes |
| If No, Relationship of the Driver with the Insured | - |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|--------------------------|
| Type of Accident | Collision - Head to Rear |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 2 |
| Was anybody injured in the Accident? | No |
| Was any injured conveyed to hospital by ambulance? | - |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 1 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |
| Translator's name | - |
| Translator's ID | - |
| Translator's phone number | - |
| Translator's email | - |
| Original language used in the statement | - |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACH

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | Yes |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--------------------|
| Vehicle Registration Number | GY247R |
| Vehicle Manufacturer | Peugeot |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Commercial vehicle |
| Name of Driver | TAN |
| NRIC No | SXXXX265A |

| | |
|---|---|
| Contact Number | (Phone) +65-97312131 |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | China Taiping Insurance (Singapore) Pte. Ltd. |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | - |

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time


 Report Centre Person's Signature
 Name
 NRIC/FIN No.

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving normal and was hit directly by 6Y247R at my rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/INID:

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

22 March 2023

| | |
|--------------------------------|-------------------|
| Estimate No. : b1 65384 | Page No. : 1 of 5 |
| Date Estimated : 22/03/2023 | |
| Prepared By : Jack Ng Guo Ming | |

| | |
|--|---|
| - ESTIMATE REPAIR FOR - ZHAO WEI 88 SENNETT AVENUE SINGAPORE 467096 | - ACCOUNT - 135 China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 |
|--|---|

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-------------|---------|
| SJJ7799L | WBY12CF080CK51594 | 17/06/2022 | iX xDrive40 | 2690 |

| DESCRIPTION | VALUE |
|---|---------------------------|
| To replace rear bumper and attachedment | 850 1,700.00 |
| To respray rear bumper. | 986 1,038.00 |
| To check electrical wiring system and lighting at the rear section for proper function. | 168 177.00 |
| To replace front or rear PDC sensor wire harness including reset and conduct check for proper function. | 168 252 266.00 |
| Sundries. | 80 / 40.00 |
| Total Labour 1: | 3,221.00 |

| DESCRIPTION | QTY | PRIC | VALUE |
|--------------------------------|-----|----------|---------------------|
| LH COVERING (FRR) ? xan | 1 | 194.65 | 194.65 |
| RH COVERING (FRR) ? xan | 1 | 194.65 | 194.65 |
| REAR BUMPER TOP der | 1 | 1,268.20 | 1,268.20 |
| REAR BUMPER BOTTOM der | 1 | 332.90 | 332.90 |
| REAR LH SIDE TRIM ? xan | 1 | 369.05 | 369.05 |
| REAR RH SIDE TRIM ? xan | 1 | 369.05 | 369.05 |
| REAR BUMPER CENTRE MOUNT ? xan | 1 | 171.90 | 171.90 |
| REAR BUMPER CARRIER ? xan | 1 | 851.70 | 851.70 |
| REAR BOTTOM COVER ? xan | 1 | 447.65 | 447.65 |
| Adapter for rear support ? xan | 1 | 151.90 | 151.90 |
| Total Parts : | | | 4,351.65 |

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

| | | | |
|----------------|--------------------|------------|--------|
| Estimate No. | : b1 65384 | Page No. : | 2 of 5 |
| Date Estimated | : 22/03/2023 | | |
| Prepared By | : Jack Ng Guo Ming | | |

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------------|------------|-------------|---------|
| SJJ7799L | WBY12CF080CK51594 | 17/06/2022 | iX xDrive40 | 2690 |

Claims OD / 3rd Party / Uninsured Inmate / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 30/05/23 @ 1100 Excess S\$ _____

Surveyor's Name PML Sign _____

Surveyor's Tel 90010668 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO P SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended 3 days

Reg IK paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

| | | | |
|--|----------------|---|-----------------|
| | Labour 1 | : | 3,221.00 |
| | Parts | : | 4,351.65 |
| | Labour 2 | : | 0.00 |
| | Excess | : | 0.00 |
| | Total GST @ 8% | : | 605.81 |
| | Grand Total | : | <u>8,178.46</u> |

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors

BMW Dealer



Final Report

Estimate No. : b1 65384
Date Estimated : 22/03/2023
Prepared By : Jack Ng Guo Ming

Page No. :

- ESTIMATE REPAIR FOR -

ZHAO WEI
88 SENNETT AVENUE

SINGAPORE 467096

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | M LEAGE |
|-----------|-------------------|------------|-------------|---------|
| SJJ7799L | WBY12CF080CK51594 | 17/06/2022 | iX xDrive40 | 2690 |

| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT |
|--|----------------|---------|---------|
| To replace top/bottom rear bumper and attachments include carrying out other necessary repairs caused by the accident | 850.00 | | 850.00✓ |
| To respray rear bumper | 986.00 | | 986.00✓ |
| To check electrical wiring system and lightings at the rear section for proper function | 168.00 | | 168.00✓ |
| To remove old PDC assembly, replace damaged parts and PDC sensors include reconnecting to new bumper and conducting checks for proper function | 168.00 | | 168.00 |
| Sundries | 80.00 | | 80.00 |

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|--------------------|------------|-------|---------|----------|
| REAR BUMPER TOP | 1,268.20 | 1.00 | 0.00 | 1,268.20 |
| REAR BUMPER BOTTOM | 332.90 | 1.00 | 0.00 | 332.90 |
| # BLIND RIVET | 1.45 | 10.00 | 0.00 | 14.50 |

SUPPLEMENTARY ITEMS

| | |
|-------------------------------------|----------|
| Total Labour : | 2,252.00 |
| Total Parts : | 1,615.60 |
| Total Labour & Parts (before GST) : | 3,867.60 |
| Deduction for Excess : | |
| Total Repair Costs less Excess: | 3,867.60 |
| GST @8%: | 309.41 |
| Grand Total : | 4,177.01 |

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 65384
Date Estimated : 22/03/2023
Prepared By : Jack Ng Guo Ming

Page No. :

- ESTIMATE REPAIR FOR -
ZHAO WEI
88 SENNETT AVENUE

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

SINGAPORE 467096

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | M LEAGE |
|-----------|-------------------|------------|-------------|---------|
| SJJ7799L | WBY12CF080CK51594 | 17/06/2022 | iX xDrive40 | 2690 |

| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT |
|-------------|----------------|---------|------|
|-------------|----------------|---------|------|

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|-------------------------|------------|-------|---------|-------|
| # BLIND RIVET <i>ms</i> | 1.45 | 10.00 | 0.00 | 14.50 |

SUPPLEMENTARY ITEMS

| | |
|-------------------------------------|-------|
| Total Labour : | |
| Total Parts : | 14.50 |
| Total Labour & Parts (before GST) : | 14.50 |

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

A  Motors Company