## COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE

Vehicle No.:

DOA

**SHC2598T** 

22.02.2023

Make Model REG.13.12.2018 PRIUS G4

Date

22.08.2022 INCOME

Insurance: MVA

CHIANG/

aty	Parts Description / Labour	Qty	Unit Price	Amount
2000年1988	The Street of the Street of the		393965	SE CONTRACTOR
1	FRONT BUMPER COVER SCC 12			8000016
1	FRT BUMPER BRACKET LH/RH X IV/V		\$ 77.00	\$154.00
10	FRONT BUMPER CLIPS XNV		s 2.20	-523.00
1	FRONT BUMPER TOW COVER			\$86.50
1	FRONT BUMPER EMBLEM X NIV			00.332
	FRONT HEAD LAMP LH ? X, NAU			\$2,637.60
1	FRONT BUMPER DAY RUNNING LH ? NO			5920.00
And in concession of the last	SUB TOTAL		Acres de la companyo	\$4,494.28
To the same of the same of	LESS 25%	THE REAL PROPERTY.		\$1,123.57
	A STATE OF THE PARTY OF THE PAR	中共用的性		\$3,370.71
	Labour Charge			
	PANEL BEATING			550.00
	SPRAY PAINTING			300.00
	TUFF COAT			60.00
	CHECK LIGHTING			60.00
	TOTAL LABOUR	<b>阿拉斯斯</b>	NOTE WENT !	\$970.00
A STATE OF THE PARTY OF THE PAR	TOTAL DESCRIPTION OF THE PROPERTY OF THE PROPE			
· · · · · · · · · · · · · · · · · · ·	ESTIMATE TOTAL	STATE OF THE PARTY OF	STATE STATE OF	\$4,340.71
STATE OF THE PARTY				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

P/P= 630X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer** 

Signature:

Date:

Pg 1