

A.S.S. REC. BY: TaufikREF: CS3/CTI 22005151/TW73**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WY' PRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKP8073YYr Regn: 2014, OctType: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz A180 c.c. 1595Colour: White A/C: Insured / Std / NI / NASp. Reading: 136525 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD1760422J300124Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NA / S/Rim / STD A/Rim orTyre Size: F: 225/40R18R: 2BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 31/5/22 2140pmSurvey held at Garage 13Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Range: 45000 - 6000, 6 days

30/03/2023 Submit L/S \$3,800.00 @ 03days (Red \$1,100/22%)

SUBMIT PRS REPORT

Date/Time, File Pass to?

30/03/2023

1) Typist

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final ReportDays Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: Paper SurveyLump Sum / L.S.: LS \$3,800

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$