

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------------|---------------------------|
| Date of Submission | 04/04/2023 09:43 (SGT) |
| Reported by | Owner |
| Date of Accident | 22/03/2023 07:30 (SGT) |
| Exact Location of Accident | Singapore |
| Additional Location Information | ESSO Station Punggol Road |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------------|----------|
| Vehicle Registration Number | SLS4077K |
|-----------------------------------|----------|

INSURED/POLICYHOLDER

| | |
|--------------------------------|-----------------------------|
| Is company? | No |
| Name Of Registered Owner | SUDIRMAN BIN SUKIMI |
| NRIC No | S2007872C |
| Email Address | Sudirmansukimi430@gmail.com |
| Mobile Phone No | (Phone) +65-91445080 |
| Alternative Phone No | - |

VEHICLE PARTICULARS

| | |
|--|---------------------|
| Manufacturer | Nissan |
| Model | Qashqai |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | - |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Reporting only |
| Vehicle Category | Private car |
| Transmission | Auto |
| CC | 1197 |

INSURANCE COMPANY

| | |
|---|--------------------------------------|
| Name of Insurance Company | AIG Asia Pacific Insurance Pte. Ltd. |
| Policy Number / Cover Note Number | 1700055382-05 |

DRIVER

| | |
|----------------------|-----------------|
| Name of Driver | Raihan Sudirman |
| NRIC No | S8206490G |
| Date Of Birth | 28/02/1982 |
| Occupation | Indoor |

| | |
|--|-----------------------------|
| Date Of Driving Pass | 17/12/2002 |
| Driving experience | 20 YEARS AND 3 MONTHS |
| Gender | Male |
| Mobile Number | (Phone) +65-85719509 |
| Alt. Phone Number | - |
| Email Address | Sudirmansukimi430@gmail.com |
| Address | 120A EDGEDALE PLAINS |
| Address complement | PUNGGOL EDGE |
| Postcode | 821120 |
| Is the driver the policyholder? | No |
| If No, Relationship of the Driver with the Insured | Child |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------------|---|
| Type of Accident | Hit and run / Vandalism / Damaged whilst parked |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 2 |
| Was anybody injured in the Accident? | No |
| Was any injured conveyed to hospital by ambulance? | - |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 1 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |
| Translator's name | - |
| Translator's ID | - |
| Translator's phone number | - |
| Translator's email | - |
| Original language used in the statement | - |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

CB7463A was stationary at the fuel pump. I was driving SLS4077K

trying to turn right to go to the parking lot. I heard a scraping sound and I reversed to adjust my position before driving to the parking lot. As I drove past CB7463A

I couldn't really see any damage done but I had intended to approach the driver of CB7463A after I parked. However after I parked

the driver drove off and left the petrol station before I could approach him. I only saw the damage to SLS4077K's front right after I finished my grocery shopping and came out of the petrol station. There was a minor scratch on the bumper and the front left wheel fender of SLS4077K was slightly unfixed.

ATTACHMENT(S)

| | |
|---|------------------------------------|
| Are accident photos available for attachment? | No |
| Was there any video captured by Car Camera? | Yes |
| Reasons for not uploading a video of the accident | INSD DID NOT PROVIDE VIDEO FOOTAGE |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|---|--------------------|
| Vehicle Registration Number | CB7463E |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Commercial vehicle |
| Name of Driver | - |
| Contact Number | - |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | - |

