



Your Ref: 202332006466

Date: 09th May 2023

Our Ref: CS6/AIS23003113/Hvp3m4

M/s Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SLW 7719B ACCIDENT ON 22/03/2023

We thank you for your instruction on 27/03/2023.

The following vehicle information was recorded:

Registration Number	: SLW 7719B
Make & Model	: Volvo S60 T2
Chassis Number	: YV1FS28L0J2461016
Year of Registration	: 2018
Engine Capacity	: 1498 cc

1. The vehicle sustained damages at the front o/s portion. (Details see photographs enclosed)
2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.