

(08/11/11) REF
ASS. R. EC. BY: /

REF:

CS6 / AIS 23003113 / Hvp3

ASSIGNMENT

420F

From: _____ Date: _____

Estimate ~~ed~~ Cost: _____

☒ OD / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Insp ~~ect~~ Vehicle No: _____

at Work ~~shop~~ m/s _____

of _____

Insured ~~ed~~: _____

Policy ~~no.~~ SP2004285087-01

Claims ~~no.~~ 202332006466

Sum Insured _____ Excess: 0

(Client's Record)

Make ~~of~~ Veh: _____

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$80K.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLW 7719 B Yr Regn: 28/2/2018

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Volvo 560 T2 c.c. 1498

Colour: Silver A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: _____ T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: YV1F82FL0J246016

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☐ Nil / ☐ S/Rim / ☒ STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 22/3/2023

D.O.I. 27/3/2023

Survey held at

Desktop Survey

Des. of Damages: ☒ Front / ☒ Rear / ☐ N/S / ☐ U/C / ☐ Rooftop or

front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Net value \$40,000

5/5/23 Lump Sum \$1850 confirmed by email (Red 1208.50, 39%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 4

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) 5/5/23-typist

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Report Format : Merimen

Lump Sum / I.B.I: (\$ 1850)

> Back to OneMotoring

D.O.A. : 22/3/2023
Bal. : 4 yrs 11-2 mths.
M.V. : \$80,000.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	420F
Vehicle Details	
Vehicle No.:	SLW7719B
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Apr 2023
Vehicle Make:	VOLVO
Vehicle Model:	S60 T2
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	B4154T52362851
Chassis No.:	YV1FS28L0J2461016
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$25,458.00
Original Registration Date:	28 Feb 2018
First Registration Date:	28 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$27,642.00 ✓
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2028 //
PARF Rebate Amount:	\$19,349.00 13,821
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$39,903.00
COE Rebate Amount:	\$19,538.00
Total Rebate Amount:	\$38,887.00

The information contained herein is correct as at 30 Mar 2023

OK

15,160

14,180

13,920

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2004285087-01	Date of Loss:	22/03/2023
Vehicle Reg. No.:	SLW7719B	Driveable?	
Driver Age/Info:	42 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Hu Cheng Chen		
Driver:	Gao Shi Fang		
Make/Model:	VOLVO S60, 1.5 T2 (A)	Vehicle Reg. Date:	28/02/2018
Vehicle Colour:	Silver		
Engine No:	YV1FS28L0J2461016	Chassis No:	YV1FS28L0J2461016
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	CITY AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,908.50
Miscellaneous Items	0.00
Labour	1,150.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,058.50
+ GST 8.00% (S\$)	244.68
Nett Amount (S\$)	3,303.18

This claim is handled by: VRONICA

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 25 Mar 2023)
Parts: 143 **VOLVO S60 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's **(Price-denominated Standard List)**
Print Code: City Auto Pte Ltd/SLW7719B/25/03/2023 10:58
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Headlamp RH	0.00	0.00	*950.00 F
2	1		*Front fender RH	0.00	0.00	*700.00 F
3	1		*Front bumper retainer RH	0.00	0.00	*85.00 F
Sub Total (S\$)						1,735.00
+ Margin on L,N Items 10.00% (S\$)						173.50
Total Parts (S\$)						1,908.50

F=Franchise part.

CUT
BAC
POLIS

City Auto Pte Ltd/SLW7719B/25/03/2023 10:58. Not valid without Reference section.
Generated using Merimen c-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	New	450.00 350
2	- Spray painting on affected and replace parts	New	700.00 500
Gross Labour Cost (S\$)			1,150.00

City Auto Pte Ltd/SLW7719B/25/03/2023 10:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Not authorise
- Excess : TBA
- P/S or L/S repair?
- Survey by Edward Lim (62563561).
- edwardlim@lkkauto.com
- Re survey before paid for P/P repair.
- 4 days to repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: