

LKK REF:	<u>CC2/MIDF23003125/Tpq2</u>	MINDEF REF:	<u>WY22/23/002</u>
TP VEH NO:	<u>GBK 1205M</u>	MINDEF VEH NO:	<u>MID41629</u>
IOD DATE:	<u>14/4/2023</u>	DATE OF ACCIDENT:	<u>16/1/2023</u>
TP INSURER:	<u>Great Eastern General Insurance Limited</u>	GOV AGENCIES:	<u>ARMY / AIR-FORCE</u>

REPAIRER:	<u>CONNECT3</u>	DATE OF INSPECTION:	<u>19/1/2023</u>
PERSON IN CHARGE:	<u></u>	INTERIM SURVEY DATE:	<u></u>
TEL NO:	<u></u>	POST REPAIR DATE:	<u></u>
PLACE OF INSPECTION:	<u></u>	RECOMMEND COR:	<u></u>
		RECOMMEND REPAIR DAYS:	<u></u>

	DATE	REMARKS:
TP POLICE/GIA REPORT	<u></u>	
MID POLICE/GIA REPORT	<u></u>	
MID PHOTOGRAPHS	<u></u>	
MID FCOR	<u></u>	
FINALIZED	<u></u>	
MANDATE	<u></u>	
TP SETTLEMENT	<u></u>	
TCA RECOVERY	<u></u>	

	UOM	UNIT PRICE	TOTAL BILLING
Documentation For Motor Accident Claim	<input type="text"/>	\$ 40.00 =	40.00
Corresponding With TP Claimant/Insurer For Recovery OR Settlement (If TCA Not Applicable)	<input type="text"/>	\$ 190.00 =	190.00
Corresponding With TP Insurer For Recovery OR Settlement (If TCA Applicable)	<input type="text"/>	\$ 120.00 =	
Liability Assessment	<input type="text"/>	\$ 20.00 =	
Conduct Searches & Purchase Report at Third-Party Government Agencies	<input type="text"/>	Reimbursed at cost =	
Appraisal of Damaged Vehicle before Repairs (On-site inspection/ appraisal, taking photos of the damaged vehicle, survey report)	<input type="text"/>	\$ 160.00 =	160.00
Appraisal of Vehicle after Repairs (On-site inspection/appraisal, taking photos, survey report)	<input type="text"/>	\$ 180.00 =	180.00
Market Valuation of the Vehicle (Without Inspection)	<input type="text"/>	\$ 15.00 =	
Market Valuation of the Vehicle (With Inspection)	<input type="text"/>	\$ 50.00 =	
Total			570.00
		8% GST	45.60
Total w/GST			615.60