(08/11/1[illegible]) wef
ASS. R[illegible]EC.BY: /

REF:

ASSIGNMENT

From: Date:

Estima[illegible]ed Cost:

OD / T[illegible] / WS / TP RES / OD RES / EVA / INV / MV

To Insp[illegible]ct Vehicle No:

at Wor[illegible]shop m/s

of

Insured[illegible]:

Policy [illegible]b.

Claims [illegible]lio.

Sum In[illegible]sured: Excess:

(Clie[illegible]'s Record)

Make [illegible]f Veh:

(Poli[illegible]y Condition)

Remar[illegible]K: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC A[illegible]ccident Rport: Consistent? : Yes or No

GIA / [illegible]PR Seen: Consistent? : Yes or No

Est. Re[illegible]pairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKU 7959Y Yr Regn: 2015 / August.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mercedes Benz CLA200 c.c 1595

Colour Black. A/C: Insured / Std / NI / NA

Sp.Reading 121245. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD1173432N151234

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18.

R: 225/40R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	07/03/23.

Survey held at HD Perfect.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Alg.
	6756.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:	
Transportation:	
__S + RS, __SI	
Photos	
Others	
TOTAL	