

ASS. REF: UBI Toughest

REF:

CS3/1CS23003187/Tg33

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp. ed Vehicle No: _____

at Work-shop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$3000

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: JSP 7907

Yr Regn: 2018 Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha

135 LC c.c. 134

Colour: Grey / Yellow

A/C: Insured / Std / NI / NA

Sp. Reading: 71858

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PMY490810 J 0002220

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / STD A/Rim or

Tyre Size: F: 70/90 R17

R: 80/90 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRI / SUMI /

TOYO / YOKO or MAXXIS

Front

Rear

R/Bal. 6 mm

R/Bal. - 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 28/2/23 @245pm

Survey held at Sports, Motor

Des. of Damages FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

REPAIR RANGE: \$2500-3500, 5 DAYS

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / L.B.I. (?) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

☐

No. Pendaftaran : JSP7907
No. ID 841125125701
Nama Pemunya Berdaftar ANDI BIN MAJID
Alamat NO 10 JALAN GELAM 14 TAMAN RINTING
81750 MASAI JOHOR
No. Chasis/No. Enjin PMYUG0810J0002220 / G305E-002240
Buatan/Nama Model YAMAHA / YAMAHA 135LC
Keupayaan Enjin 134
Bahan Bakar PETROL
Status Asal PEMASANGAN TEMPATAN
Kelas Penggunaan MOTOSIKAL
Jenis Badan/Tahun Dibuat MOTOSIKAL / 2018
Tarikh Pendaftaran 07.02.2018
B D M E G Y BTM
Syarat Pendaftaran 1
Syarat Pendaftaran 2
Syarat Pendaftaran 3



SINGAPORE POLICE FORCE

①



T/20230318/2048

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 3

Report No. T/20230318/2048

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/03/2023 15:36		Vide Report No.:	Station Diary No.: 75
Informant's Particulars			
Name of Informant: ANDI BIN MAJID		Address: 780E WOODLANDS CRESCENT WOODLANDS DEW	
ID Type / ID No.: FIN NO / G7564313L		Contact No.: Home/Office: Mobile: 82847148	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 38	Date of Birth: 25/11/1984	Type of Informant: Rider
Race: Malay		Language: English	
Occupation: CONSTRUCTION		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 11/03/2023 17:10	Type of Location: Straight Road
Location: WOODLANDS CHECKPOINT VIADUCT				
Weather: Clear		Road Surface: Dry		
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JSP7907	Motorcycle					0
SKC9759P	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20230318/2048

Police Station Of Origin:

Yishun North N.P.C

31 Yishun Central SINGAPORE 768827

Tel No: 1800-8529999

2 of 3

Report No. T/20230318/2048

CONTINUATION OF REPORT

Rider			
Name	ANDI BIN MAJID	ID No.	G7564313L
Related Vehicle	JSP7907 (Motorcycle)	Contact No.	82847148
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	11/03/2023	Date Discharge	18/03/2023
No. of Days granted Medical Leave	22	Degree of Injury	Serious

Brief Details.

11/03/2023 around 1710hrs to 1715hrs I was riding my motorcycle bearing plate number JSP7907 along Woodlands Checkpoint Viaduct, towards Woodlands checkpoint.

I was riding on the motorcycle lane and there was a slight right turn, at that moment when I turned, there was this car, bearing car plate, SKC9759P that was driving in the motorcycle lane. I tried to emergency brake however was unable to react in time and I collided onto the left side of the car, I was then thrown off my motorcycle from the impact.

I could not recall what happened afterwards as I passed out from the collision.

I was then admitted to Khoo Teck Puat Hospital for my injuries from 11/03/2023 to 18/03/2023.

I sustained the following injuries:

Right femur fracture and Right little finger laceration.

I was also given 22 days of MC (REF number: 1390865841)



**SINGAPORE
POLICE FORCE**



T/20230318/2048

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3

Report No. T/20230318/2048

CONTINUATION OF REPORT

Signature of Officer Recording The Report:

L /

SGT 2 CELINA TOO SI LING

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

STAFF SGT NUR HAFIZAH BINTE NORIZAN

Contact No.: 96189347

Signature Of Informant:

Date/Time:

18/03/2023 15:36

Classification Of Case: