



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI23003211/Uwy3e2 Date: 05/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 6485X	Veh. Inspected	GBK 3364Z	
Policy No.	D-22099843MFBP	Coverage (\$)	0.00	
Claim No.	D23001025MFBP	Excess (\$)	0.00	
Assign From	CAROLINE CABRERA	Assign Date	28/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 DX (A)	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	VM20138059	Colour	GREY	
Odometer	69802 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	ROADSTONE	6 mm	
L/H Front Tyre	175/70 R14	ROADSTONE	6 mm	
R/H Rear Tyre	175/70 R14	ROADSTONE	6 mm	
L/H Rear Tyre	175/70 R14	ROADSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/03/2023	Inspection Date	29/03/2023	
Survey held at	SAM YICK LIAN 1, KAKI BUKIT AVE 6 #01-70 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	