KAH YEN



MOTOR SURVEY ASSIGNMENT

**Date** 28/03/2023 **Our Ref No.** D23001025MFBP

Accident Date 22-03-2023 Claim Type Third Party

Insured Vehicle SBS6485X Third Party Vehicle GBK3364Z

Survey Location HUA MENG SPRAY PAINTING Contact Person

**WORKSHOP** 

1 KAKI BUKIT AVENUE 6 BLOCK C, #01-61 / #01-34 (S) 417883

**Contact No.** 67465519 **Fax No.** 67434896

Survey Type Without Prejudice

Appointed LKK AUTO CONSULTANTS PTE LTD

Surveyor LKK AUTO CONSULTANTS PTE LTL

Contact Person Fax No. 68416315

Contact Number 62563561

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

WP

Cc: Workshop HUA MENG SPRAY PAINTING WORKSHOP Attention KAH YEN

Officer Incharge RACHELWU

## **IMPORTANT NOTE**

Kindly submit the survey report by **email only** to <u>surveyor@msfirstcapital.com.sg</u> within 14 days for survey assignment and 7 days for re-inspection.