

Our Job Ref No 1 305549037							
Date : 06.04.2023				ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969			
FINA	LIZAT	ION FORM					
То	: _		LKK	Fax:			
Attn	Attn : IRFAN						
Vehic	cle Re	No. : SHB	2337K		18.03.2023		
The :	survey	and estimates o	f the repairs of the above-me	ntioned vehic	e are as follow	/s:-	
Z	The	repair job shall b	ill to:	CHINA SDX68G			
2.	The finalized amount shall be:						
	(a)	(a) Spare Parts after List discount					
	(b)	Labour Charge	es				
		Total for Part-By-Part Repair Cost				0	
	(c.)	(c.) Lumpsum Repair (if applicable)					
	(0.)	Total for Lumps		_	<u> </u>		
		Final Lumpsu	m Repair Cost			\$1,200.00	
Estimated normal period for repairs:			iod for repairs:	2w	orking days.		
4.			ove amount as Correct and	d Confirmed i	f there is no r	eply from you within	
		rking days					
5. Thank you for your ass			sístance.	We confirm the estimates and finalized amount			
			4				
	Simplify /			Circultura			
	Signature : CHIANG				Signature:		
A 2				Name :			
Tel : 62148314 Date					ite ;		
	Fax	6546815	00	-			
For O	fficial	Use Only					
	ı	tem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
Rental Rate P/Day				YES			
2. Loss of Income Paid			#	N			
3. Survey Fees				::::			
4. LTA Search Fee 5. Medical Fees (on behalf			\$26.75/\$2.00	YES			
of driver, if applicable)							
	errun						
Remar	ks:						