

REF:

ASS. REC. BY:


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: CTI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GIA / PR Score: _____ Consistent? Yes or No
 Est. Repairs: 2 days Rest: Yes or No
 Lump Sum: 90 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN/OUT

Veh No: Sh 7969.5 Yr Reg: 07/1/2019
 Type: M/Gar / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai cc: 1580
 Colour: Blue AC: Insured / Std / PFI / NA
 Sp. Reading: 323313 YR/Date: Insured / Std / PFI / NA
 Eng/No: _____
 C/Nr: Kmh18572ULVL87900
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inoper / Jammed / Leaked / Burnt or
 Brake: Inoper / Jammed / Leaked / Burnt or
 Mod: N/S / S/Rim / STD / R/Rim, or
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EDNOVA / GY / FS / LZA / M/C / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front: _____ Rear: _____
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A. 15/3/23 D.O.I. 17/3/23 lpm
 Survey held at Comfort
 Des. of Damages: Fnt / Rear / O/S / N/S / WC / Rooftop or
FRONT O/S
 The WC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / LBJ: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transport:

3 + 12.13

Photo

Other

TOTAL

Date/Time: 16.03.2023 13:53

Page: 1

Sam: ARC Repair TP(CLB0)1

JOB CARD

Sales Order: 5009693

JO: NC005548800

TOMER

AS COMFORT TRANSPORTATION PTE LTD

TOMER NO 7010045

RESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(P) 65508755

(D)

(P)

OUNT CARD NO.

REGN NO

SH 7969S

MILEAGE

MAKE

HYUNDAI

FUEL

E 10 F

MODEL

IONIQ (G3)

DATE/TIME IN 16.03.2023 09:50

YR OF MANUF

07.11.2019

TARGET DATE

CHASSIS CODE

KMEC851CNUJ187900

COMPLETION DATE/TIME

ccident Date: 15.03.2023


ATURE: 3P 15.03.2023

JOB DESCRIPTION

/NO

LABOR CODE

DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

Vehicle No.: SH 7969S

CHIANG

Vehicle No.:

SH 7969S

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard