SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process

- 1. Flease report <u>controlling</u> are details of the accident to speed up the Colling process.

 2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 16/03/2023 12:47 (SGT) Reported by 15/03/2023 18:25 (SGT) Date of Accident ... Exact Location of Accident Bedok North Rd, Singapore **TOWARDS TAMPINES** Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Hyundai

1580

SH7969S Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD Company Reg No 1XXXXX821R **Email Address** fleetsafety@cdgtaxi.com.sq Mobile Phone No (Phone) +65-92986112 Alternative Phone No (Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer

Model Ae ioniq Variant Exact purpose for which vehicle was being used at time of Private hire accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Taxi Transmission Auto

INSURANCE COMPANY

Name of Insurance Company HSBC Life (Singapore) Pte. Ltd Policy Number / Cover Note Number VFX/P2419138

DRIVER

CC

Name of Driver **BENNY LIM HAI LENG NRIC No** SXXXX178E Date Of Birth 17/06/1964 Occupation Outdoor

Accident report SJ0G233G000I

Page 1 of 15

Date Of Driving Pass 28 YEARS AND 8 MONTHS **Driving experience** Gender Male Mobile Number (Phone) +65-92986112 Alt. Phone Number fleetsafety@cdgtaxi.com.sg **Email Address BLK 725 TAMPINES STREET 71 # 12-165** Address Address complement 520725 Postcode Is the driver the policyholder? No If No. Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No

Insurance Company of Other Vehicle Owned by Driver

Vehicle Registration Number of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s)	
soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	- 1 -
Translator's email	-
Original language used in the statement	1/1-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	

CIRCUMSTANCES OF ACCIDENT

ON 15,03,2023 AT ABOUT 1825HRS I WAS DRIVING MY VEHICLE A SH7969S ON THE 3RD LANE OF BEDOK NORTH ROAD TOWARDS TAMPINES, AT THE TRAFFIC LIGHTS JUNCTION OF BEDOK RESERVOIR ROAD, VEHICLE B SKZ3218C ON MY RIGHT ON AN ONLY RIGHT TURN LANE, CUT INTO MY LANE. HER VEHICLE B LEFT THEN SIDE SWIPE MY VEHICLE A RIGHT FRONT.

UPON IMPACT I HURT MY NECK AND SHOULDER. SCENE PHOTOS AND PARTICULARS TAKEN, NO HANDPHONE EXCHANGED.

ATTACHMENT(S)

cid

Acc

Are accident photos available for attachment?

Was there any video captured by Car Camera?


Reasons for not uploading a video of the accident

FILE NOT SUITABLE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKZ3218C
Vehicle Manufacturer Volvo

Page 2 of 15





Page 3 of 15



Vehicle Model Vehicle Variant Vehicle Colour Private car Vehicle Category TOCK CI EN, VALERIE (ZHU CI'EN) Name of Driver SXXXX132I NRIC No Contact Number Address Address complement Postcode Insurance Company Name LEFT SIDE Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)


INJURED PERSONS DETAILS

INJURED 1

Was this injured conveyed to hospital by ambulance?

BENNY LIM HAI LENG Name of injured person Gender (Phone) +65-92986112 Phone No **BLK 725 TAMPINES STREET 71 # 12-165** Address Address Complement 520725 Post Code 58 Approximate Age Years Old **NECK AND SHOULDER** Injuries Sustained SH7969S Injured person in which vehicle? Yes Were seat belts worm?

Page 3 of 15





SKETCH PLAN

IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts mayallow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurancecompanies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectivelyreferred to as the "insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims.
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (M) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involvedisclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(Collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Driver's Signature (If driver is not the policyholder) / Date& Time 16.03.2023. 1040HRS


KYMIYONG Witnessed by Reporting Centre

FLASH ACCIDENT

Personnel

Policyholder's Signature / Date & Time

Sketch Plan



Accident report SJ0G233G000I

Page 4 of 15

Page 5 of 15

Describe Circumstances of the Accident

ON 15.03.2023 AT ABOUT 1825HRS I WAS DRIVING MY VEHICLE A SH7969S ON THE 3RD LANE OF BEDOK NORTH ROAD TOWARDS TAMPINES. AT THE TRAFFIC LIGHTS JUNCTION OF BEDOK RESERVOIR ROAD, VEHICLE B SKZ3218C ON MY RIGHT ON AN ONLY RIGHT TURN LANE, CUT INTO MY LANE. HER VEHICLE B LEFT THEN SIDE SWIPE MY VEHICLE A RIGHT FRONT. UPON IMPACT I HURT MY NECK AND SHOULDER. SCENE PHOTOS AND PARTICULARS TAKEN. NO HANDPHONE EXCHANGED.

Declaration

Date &Time

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature /

Driver's Signature (If driver is not the policyholder) / 1045HRS Date& Time 16.03.2023.

FLASH ACCIDENT KYMI YONG

Witnessed by Reporting Centre Personnel