Anna (Asum)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 06.03.2023
Time: 13:44:56
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305547364
REGN NO	:	SHD3571H
MILEAGE	:	0000000000
MAKE	:	HYUNDAI
MODEL	:	IONIQ(G2)
DATE OF REGN	:	12.07.2018
DATE/TIME IN	:	06.03.2023 09:25
ACCIDENT DATE	:	05.03.2023

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
PART REQUISITION					
0001 04-01-0104-2915-A LAMP ASSY-HEAD RH#	1		2,110.30	20.00	1,688.24 Scr
0002 04-01-0104-3918-G BRACKET-FR BUMPER SIDE RH	1		35.00	20.00	~~28.00~~ ? XNN
0003 04-01-0104-2534-G COVER-FR BUMPER#	1		481.10	20.00	384.88 Scr
0004 04-01-0104-2361-G MOULDING-FRONT BUMPER CTR	1		368.50	20.00	294.80 Scr
0005 04-01-0101-0111-G BUMPER COVER CLIP ~~REAR~~ Front	10	L	22.00	20.00	17.60 Nil
				SUB-TOTAL :	2,413.52
JOB NATURE					
0000 L PANEL BEATING					400.00 350
0001 SP SPRAYPAINT CHARGE					300.00 250
0002 17-01 CHECK ALL LIGHTING					50.00 30
				SUB-TOTAL :	750.00

F = 3018.52

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

20% = 603.10
~~2412~~
~~2400~~ Irfan

Lacquering
2 days
L/S
6/3/23 4pm

Scanned with CamScanner