

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

China (Usun)

Date: 06.03.2023

Time: 13:44:56

Page: 1

JH

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305547364  
 REGN NO : SHD3571H  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 12.07.2018  
 DATE/TIME IN : 06.03.2023 09:25  
 ACCIDENT DATE : 05.03.2023

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|      |                   |                                            |      |          |       |                        |                      |
|------|-------------------|--------------------------------------------|------|----------|-------|------------------------|----------------------|
| 0001 | 04-01-0104-2915-A | LAMP ASSY-HEAD RH#                         | 1    | 2,110.30 | 20.00 | 1,688.24               | Scr ✓                |
| 0002 | 04-01-0104-3918-G | BRACKET-FR BUMPER SIDE RH                  | 1    | 35.00    | 20.00 | <del>28.00</del> ? XAU |                      |
| 0003 | 04-01-0104-2534-G | COVER-FR BUMPER#                           | 1    | 481.10   | 20.00 | 384.88                 | Scr ✓                |
| 0004 | 04-01-0104-2361-G | MOULDING-FRONT BUMPER CTR                  | 1    | 368.50   | 20.00 | 294.80                 | Scr ✓                |
| 0005 | 04-01-0101-0111-G | BUMPER COVER CLIP <del>REAR</del><br>Front | 10 L | 22.00    | 20.00 | 17.60                  | Scr ✓                |
|      |                   |                                            |      |          |       |                        | SUB-TOTAL : 2,413.52 |

## JOB NATURE

|            |                    |                    |     |
|------------|--------------------|--------------------|-----|
| 0000 L     | PANEL BEATING      | 400.00             | 350 |
| 0001 SP    | SPRAYPAINT CHARGE  | 300.00             | 250 |
| 0002 17-01 | CHECK ALL LIGHTING | 50.00              | 30  |
|            |                    | SUB-TOTAL : 750.00 |     |

F = 3018.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

20/6 = 603.10

2412

22140011

1rfm

Late with

2 days

L/S

6/3/23 4pm