

(08/11/13) wel

ASS. REC. BY: John

REF:

CS3/AK 23003277/Rqy3

637B

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBT 2417Pat Workshop m/s SPEEDWAYof 36, POH Guan RD POST #01-32Insured: ALL

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 15K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBT 2417P Yr Regn: 2021 DK

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YANFAN MAX 155 ABCCT c.c. 155Colour: RED A/C: Insured / Std / NI / NASp. Reading: 16417 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: M#2SG5680MK163714Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 110/70-13R: 130/70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or IRC

Front: _____ Rear: _____

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 28/03/23 D.O.I. 29/03/23Survey held at SPEEDWAYDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT 6.5K

ESTIMATE REPAIR RANGE / 160.00 days - (4K-5K) / 4 days

03/05/23 Submit DAR

Date/Time, File Pass to?

☐ : Prell. Report

1) 03/05 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) S + RS SI

) Photos

) Others

Report Format: MER-DAR

Lump Sum / I.B.I: (\$) _____)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 637B

Vehicle Details

Vehicle No.: FBT2417P

Vehicle to be Exported: No

Intended Deregistration Date: 29 Mar 2023

Vehicle Make: YAMAHA

Vehicle Model: NMAX 155 ABS CVT

Primary Colour: Red

Manufacturing Year: 2021

Engine No.: G3L8E0769235

Chassis No.: MH3SG5680MK103714

Maximum Power Output: -

Open Market Value: \$2,888.00

Original Registration Date: 17 Dec 2021

First Registration Date: 17 Dec 2021

Transfer Count: 1

Actual ARF Paid: \$434.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Dec 2031

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$9,401.00

COE Rebate Amount: \$8,190.00

Total Rebate Amount: \$8,190.00

Yamaha Nmax 155

Listing Type

Paid Ad

Brand

Yamaha

Model

Yamaha Nmax 155

Engine Capacity

155cc

Classification

Class 2B

Registration Date

10/06/2021

COE Expiry Date

09/06/2031

(8yrs 2mths 11days COE left)

Mileage

-

No. of owners

-

Type of Vehicle

Scooters

SGD **\$14500**