

AIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 29 Mar 2023)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	ComfortDelGro Engineering Pte Ltd/SHA6121U/29/03/2023 14:03		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT DOOR ASSY RH Ser R	25.00	0.00	*1,264.00 FL
2	1		*REAR DOOR ASSY RH Ser R	25.00	0.00	*1,258.30 FL
3	1		*FRT DOOR COMFORT LOGO nil	0.00	0.00	*75.00 F
4	1		*REAR DOOR APPS LOGO nil	0.00	0.00	*80.00 F
Sub Total (S\$)						2,677.30
- List Item Discount on L Items (S\$)						630.58
Total Parts (S\$)						2,046.72

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHA6121U/29/03/2023 14:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1		OD/TP Case (Insurer)	11.00 ✓
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	700 1,000.00
2	SPRAYPAINT	New	750 1,000.00
3	TRANSFER DOOR PARTS	New	240.00
Gross Labour Cost (S\$)			2,240.00

ComfortDelGro Engineering Pte Ltd/SHA6121U/29/03/2023 14:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FT = 1616

3 days PIP
30/3/23
3 pm 8/10km

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: